

Report of Survey for Repairs, &c., of Engines and Boilers.

TUES, 15 MAR 1898

(Received at London Office)

Date of writing Report *March 14 1898* When handed in at Local OfficeNo. in Reg. Book. *22* Survey held at *London*Date, First Survey *March 11* Last Survey *March 12 1898*on the Machinery of the *Wood, Iron or Steel* *S.S. "Londonian" (ex "Idaho")* Master *Marshall*Tonnage { Gross *3532* Net *3614* Vessel built at *Glasgow* By whom *A. Stephen & Sons* When *1896* YEAR. MONTH. *4*Registered Horse Power *660* Engines made at *Do.* When *1896* Boilers, when made (Main) *1896* (Donkey) *1896*No. of Main Boilers *1* Owners *Wilson, & James - Leyland Line* Port *Auld* Voyage *Boston*No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *R. Albert Dock* (State name of Dock.)Steam Pressure in Main Boilers *180 lbs* in Donkey Boilers *80 lbs* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).Last Survey No. *Port*Particulars of Examination and Repairs (if any) *Tunnel Shap.*

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " " " *No*If this was not done, state for what reasons? *Survey not due.*

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? *No* At what pressure were they afterwards adjusted under steam? *✓*Did the Surveyor examine the Safety Valves of Donkey Boiler? *No* To what pressure were they afterwards adjusted? *✓*Has the propeller shaft been drawn and examined at this time? *No* If spare propeller shaft fitted, state whether new? *✓*

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? *Completed.*

The defective length of Tunnel shapping mentioned in the London report No 59581, has now been removed and a new length fitted.

General Observations, Opinion, and Recommendation:— *This Vessel's Machinery is now as*

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, E.&M.S. 9,97 or L.M.C. 9,97, 140 lb., F.D., &c.)

far as seen is good condition & in my opinion the vessel is eligible to remain as classed

Office or Registration Fee (per Sec. 27)..... £ : : Fees applied for
Survey Fee (per Section 28)..... £ : :
Special Damage Fee (per Section 28)..... £ : :
Travelling Expenses (if chargeable)..... £ : :
Received by me, *18*

State if Certificate is required

Committee's Minute *FRI, 18 MAR 1898*Assigned *As now*

Lloyd's Register Foundation

LON 715-0054

One length of tunnel shafting

unweld.

It is submitted that
this vessel is eligible to
remain as CLASSED.

LL
18/3/98

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation