

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office THUR, 17 MAR 1898)

Writing Report March 15 98 When handed in at Local Office 18 Port of London

Survey held at London Date, First Survey and Last Survey March 12 1898

688 on the Machinery of the Wood, Iron or Steel S.S. "Michigan" Master Subr.

Tonnage { Gross 3712 Net 2853 Vessel built at Belfast By whom Harland Wolff & Co. When 1890. 6. Registered Horse Power 390 Engines made at 80 When 1890 Boilers, when made (Main) 1890 (Donkey) 1890. No. of Main Boilers 2 Owners National S.S. Co. Ltd. Port London Voyage New York No. of Donkey Boilers 1 Steam Pressure 180 lbs. If Surveyed in Dry Dock Albert Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. Port Particulars of Examination and Repairs (if any) Docking.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No. Do. " Donkey " " " Survey not due.

If this was not done, state for what reasons? And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? No At what pressure were they afterwards adjusted under steam? No

Did the Surveyor examine the Safety Valves of Donkey Boiler? No To what pressure were they afterwards adjusted? No

Has the propeller shaft been drawn and examined at this time? No If spare propeller shaft fitted, state whether new? 15 July.

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? Completed.

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Examined propeller, stern bush, & sea connections fastenings, found same all in good condition.

General Observations, Opinion, and Recommendation:—This vessel's Machinery is now (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, B.&M.S. 9,97 or S.L.M.C. 9,97, 140 lb., F.D., &c.) as far as sea is good condition & in my opinion the vessel is eligible to remain as classed.

Office or Registration Fee (per Sec. 27) £ : : Fees applied for Survey Fee (per Section 28) £ : : 18 Special Damage Fee (per Section 28) £ : : Received by me, Travelling Expenses (if chargeable) £ : : 18

*State if Certificate is required Committee's Minute Assigned FRI, 18 MAR 1898

Assigned

LON 715-0063

*It is submitted that
this vessel is eligible to
remain as CLASSED.*

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

*7/2
17/3/98*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation