

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office.

MON 20 JUN 1898

Date of writing Report *18 June 1898* When handed in at Local Office *18 June 1898* Port of *London*
 No. in Reg. Book. *534* Survey held at *London* Date, First Survey *13 June 1898* Last Survey *13 June 1898*
 on the Machinery of the Wood, Iron or Steel *J.S. Iron* Master *J. Dunn*
 Tonnage Gross *5610* Net *3647* Vessel built at *Belfast* By whom *Harland & Wolff* When *1892* 5-
 Registered Horse Power *429* Engines made at *Donkey* Boilers, when made (Main) *92* (Donkey) *92*
 No. of Main Boilers *2* Owners *J. Dixon & Sons* Port *Belfast* Voyage *Baltimore*
 No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Afloat in R.I. Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 Steam Pressure in Main Boilers *180 lb* in Donkey Boilers *180*

Last Survey No. *59230* Port *Lon*Particulars of Examination and Repairs (if any) *B.S.*

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done

On vessel's return to L. H. in six weeks. Donkey Boilers to be examined and all Safety Valves adjusted under steam. Now done. Main Boilers examined throughout and found to be generally in good condition.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, B.&M.S. 9,97 or L.M.C. 9,97, 140 lb., &c.)

The Machinery of this vessel is in good order and in my opinion eligible to remain as classed and a fresh record of B.S. 6,98 assigned when this Survey is completed. Letter to Owners.

Office or Registration Fee (per Sec. 27) £ *2*
 Survey Fee (per Section 28) £ *2*
 Special Damage Fee (per Section 28) £ *4*
 Travelling Expenses (if chargeable) £ *1.16.0*

Fees applied for

20/6 1898

Received by me,

2.7.1898

State if Certificate is required

Committee's Minute *TUES. 21 JUN 1898*

Assigned

Deferred for compl. of B.S.

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



Lloyd's Register Foundation

LON715-0463

B.S. due 5.98 will be completed
in six weeks.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this
vessel WILL BE eligible for
the record. B.S. 6.98 when
the donkey boiler & its
safety valves have been
examined & all
the safety valves
adjusted under
steam.

H.S.

20.6.98

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation