

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

(Received at London Office

WED. 27 JUL 1898

Date of writing Report *July 25 1898* When handed in at Local Office *is* Port of *London*  
 No. in *Book* Survey held at *London* Date, First Survey *and* Last Survey *July 25 1898*  
 1033 on the Machinery of the *Wood, Iron or Steel* *S.S. Star of England* Master *Weech*  
 Tonnage { Gross *3782* Net *2432* Vessel built at *Belfast* By whom *Workman Clark & Co. Ltd* When *1889* YEAR. MONTH.  
 Registered Horse Power *367* Engines made at *Glasgow* When *1889* Boilers, when made (Main) *1889* (Donkey) *1889*  
 No. of Main Boilers *2* Owners *J. P. Carry & Co* Port *Belfast* Voyage *New Zealand*  
 No. of Donkey Boilers *1* If Surveyed *in Dry Dock* *A. A. Dry Dock*  
 Steam Pressure *160 lbs*  
 in Main Boilers *160 lbs*  
 in Donkey Boilers *90 lbs*

Last Survey No. Port

Particulars of Examination and Repairs (if any) *Docking*

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

*Examined propeller, stern bush, & sea connections & fastenings, found same all in good condition.*

General Observations, Opinion, and Recommendation:— *This vessel's Machinery is now*

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, B.&M.S. 9,97 or L.M.C. 9,97, 140 lb., F.D., &c.)

*as far as seen is good condition & in my opinion the vessel is eligible to remain as classed.*

	£	s	d	Fees applied for
Office or Registration Fee (per Sec. 27)				18
Survey Fee per Section 23				
Special Damage Fee (per Section 28)				
Travelling Expenses (if chargeable)				18

Received by me,

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

State if Certificate is required

Committee's Minute

Assigned

TUES. 2 AUG 1898



© 2019

Lloyd's Register Foundation

LON 716 - 0165



It is submitted that this vessel is eligible to remain as **CLASSED**.

41.  
3/7/48

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN