

Report of Survey for Repairs, &c., of Engines and Boilers.

WED, 24 AUG 1898

Date of writing Report *Aug 23, 1898* When handed in at Local Office *18* Port of *London*
No. in Reg. Book. *465* Survey held at *London* Date, First Survey *Aug. 17th* Last Survey *Aug 23, 1898*
465 on the Machinery of the ~~Wood, Iron or Steel~~ *P.P. Matatua* Master *Hans*
Tonnage { Gross *3393* Net *2173* Vessel built at *Nure* By whom *Stephenson & Co.* When *1890* 1.
Registered { Horse Power *329* Engines made at *Hpl.* When *1890* Boilers, when made (Main) *1890* (Donkey) *1890*
No. of Main Boilers *2* Owners *Shaw, Savill, & Albion Co. Ltd* Port *Southampton* Voyage *New Zealand.*
No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Victoria St.*
Steam Pressure— *160 lbs* in Main Boilers
in Donkey Boilers *80 lbs*

Last Survey No. *59729* Port *Lon*
Particulars of Examination and Repairs (if any) *Steam pipes.*
Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.


Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *No*
Do. " Donkey " " " " " *No*
If this was not done, state for what reasons? *Survey not due*
And what parts of the Boilers could not be thus thoroughly examined?
Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler?
Did the Surveyor examine the Safety Valves of the Main Boiler? *No* To what pressure were they afterwards adjusted under steam? *✓*
Did the Surveyor examine the Safety Valves of Donkey Boiler? *No* To what pressure were they afterwards adjusted under steam? *✓*
Has the propeller shaft been drawn and examined at this time? *No* If spare propeller shaft fitted, state whether new? *✓*
State the distance between lignum vitæ of stern bush and top of after bearing of screw shaft?
If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Completed.
Tested Main Steam pipes by hydraulic pressure to 320 lbs.
Upper length leaked slightly at flange. Has recharged and retested.
Pipe annealed

General Observations, Opinion, and Recommendation:— *This vessel's machinery is now as far as seen in good condition & in my opinion the vessel is eligible to remain as classed.*

Office or Registration Fee (per Sec. 27)..... £ : : Fees applied for
Survey Fee per Section 28)..... £ : : 18
Special Damage Fee (per Section 28)..... £ : :
Travelling Expenses (if chargeable)..... £ : :
Received by me, *Jm Salmon*
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required
Committee's Minute *FRI. 26 AUG 1898*
Assigned *As now*



Main steam pipes repaired & tested

It is submitted that
this vessel is eligible to
remain as CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

HL
24/10/98

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation