

Report of Survey for Repairs, &c., of Engines and Boilers.

No. 60239

MUN 29 AUG 1898

(Received at London Office)

Port of London

18

Date of writing Report 27 Aug 1898 When handed in at Local Office

Date, First Survey

Last Survey 18 Aug 1898

No. in Reg. Book. Survey held at London

S. S. "Vaux hall" Master A. W. Wood

Tonnage Gross 817 Net 528

Vessel built at Newcastle

By whom Palmer & Co.

When 1878 Boilers, when made (Main) 1878 (Donkey) 1886

Registered Horse Power 99

Engines made at Newcastle

When 1878 Boilers, when made (Main) 1878 (Donkey) 1886

No. of Main Boilers one

Owners Rivers Steam Colliers Co Ltd Port London

Voyage

No. of Donkey Boilers one

Surveyed in Dry Dock

Union

Steam Pressure in Main Boilers 75 lb

in Donkey Boilers 80 lb

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Year and Month when last surveyed.	Machinery and Boiler Surveys (including date of N.B., if any).
+	90 A1-8-98	LC 12-94
SS	SL 4-3-9-90	BS 1-98
SS	Nwe 4-1-94	

Last Survey No.

Port

Particulars of Examination and Repairs (if any) Damage

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " No

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Has the propeller shaft been drawn and examined at this time? No If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? 1/8

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Examined Propeller, Stern Bush & all fastenings in dry dock & found them satisfactory

General Observations, Opinion, and Recommendation:—The Machinery of this vessel, (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,07, B.&M.S. 9,07 or L.M.C. 9,07, 140 lb., F.D., &c.)

As far as seen, is now in a safe working condition & eligible in my opinion, to remain as classed

	Fees applied for
Office or Registration Fee (per Sec. 27).....	£ 18
Survey Fee per Section 28).....	£ 18
Special Damage Fee (per Section 28).....	£
Travelling Expenses (if chargeable).....	£

Thomas R. Blackie.
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

State if Certificate is required

Committee's Minute

Assigned

FRI. 2 SEP 1898

FRI. 3 MAR 1899

TUES. 18 JUL 1899

© 2019

Lloyd's Register Foundation

~~1. 1. 10~~

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

11/9/1988

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

© 2019

Lloyd's Register
Foundation