

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office NOV 14 NOV 1898)

Date of writing Report 18 When handed in at Local Office 18 Port of *London*

No. in Reg. Book. *136* Survey held at *London* Date, First Survey *1.1.90* and Last Survey *5.11.98*

on the Machinery of the Wood, Iron or Steel Master *Thurman*

Tonnage Gross *2255* Net *1437* Vessel built at *Whitby* By whom *J. Turnbull & Son* When *1889* 12

Registered Horse Power *217* Engines made at *Sheffield* When *'89* Boilers, when made (Main) *'89* (Donkey) *'89*

No. of Main Boilers *2* Owners *Mrs. Brightman & Co* Port *London* Voyage *to India*

No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Afloat in London* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Steam Pressure in Main Boilers *160 lb* in Donkey Boilers *70*

Last Survey No. *37461* Port *London*Particulars of Examination and Repairs (if any) *Completed U.C. + 100 A. 9.97. + L.M.C. 11.98.*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam? *162 lb.*

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam? *68 lb.*

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the survey is not complete state what arrangements have been made for its completion and what remains to be done?

Now done: - Main and Donkey Boilers adjusted under steam as above.

Please see N.ell Report No. 37461.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, B.&M.S. 9,97 or L.M.C. 9,97, 140 lb., F.D., &c.)

The Machinery of this vessel is in good order and in my opinion eligible to remain as classed and this survey being now completed to have fresh period of + L.M.C. B.S. - 10.98.

	£	s	d	Fees applied for
Office or Registration Fee (per Sec. 27)				18
Survey Fee per Section 28				
Special Damage Fee (per Section 28)				
Travelling Expenses (if chargeable)				18

State if Certificate is required

Committee's Minute


FRI. 18 NOV 1898

Assigned

+ L.M.C. 10.98

Richie

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



Lloyd's Register
Foundation

LON717-0022

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD. *LMC-10.98.*

A.C.H.

15.11.98.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation