

TUES. 7 MAR 1899

No. 60807

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18 Port of London
 No. in Survey held at London Date, First Survey 27 Feb Last Survey 3 Mar 18 99
 Reg. Book. 162 on the Wood, Iron or Steel Iron Ship "Derwent" Master W. W. Smith
 TONNAGE:— Built at Dumbarton By whom H. Killan & Co When 1884 10
 GROSS 1970 Owners Switt & Moore Port belonging to London
 UNDER DEK 1805 Owners' Address
 NET 1890 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage Lydney
 WB=CellDBorDBa feet; uE&B feet; J feet; }
 total capacity tons. FPT tons; APT tons; MT feet tons. }
 N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 227 Port Syd

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+150 A 1 9 98 S S Syd 20310.96		

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Equipment.

The second Ridge anchor (not required by the rules) reported in Lydney report 20 887 to have been used in making temporary repairs has now been replaced by a new tested anchor.
 2nd of Certificate 41691 L.P. & Hetherton weight of anchor 5-1-0, stock 1-0-7. Test 5-14-1-14 (sgd) H. Green

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

PRESENT CONDITION OF THE

Decks <u>Good</u>	Stringers <u>not seen</u>	Engine Room Skylights <u>—</u>	Boats <u>Good</u>
Caulking of Decks <u>"</u>	Inner Bottom Plating <u>—</u>	Coal Bunkers, Open'gs, Lids, &c. <u>—</u>	Masts, Yards, &c. <u>"</u>
Waterways <u>"</u>	State if Tanks now tested <u>—</u>	Scuppers <u>Good</u>	Condition, how ascertained <u>from deck</u>
Coamings <u>"</u>	Bulkheads <u>4</u>	Cargo Hatchways <u>"</u>	(State if wedges removed <u>no</u>)
Beams & Fastenings <u>not seen</u>	Ceiling <u>"</u>	Hatches <u>"</u>	Sails <u>Good</u>
Outside Plating <u>part seen good</u>	Cement or Asphalt (State which.) <u>"</u>	Planking of Wood Vessels <u>"</u>	Equipment letter <u>✓</u>
Caulking of ditto <u>"</u>	Rudder <u>"</u>	Treenails ditto	Anchors, No. of <u>3B 1 S 2 K</u>
Rivets <u>"</u>	Windlass <u>"</u>	Breasthooks & Stemson ditto	Cables (State if now ranged) <u>no</u>
Breasthooks & Crutches <u>not seen</u>	Have Pumps now been examined and found efficient? <u>—</u>	Transoms, Pointers, & Crutches ditto	" length (on board) size <u>—</u>
Transoms <u>"</u>	Have Sluice Valves now been examined and found efficient? <u>—</u>	Timbers of Frame at openings ditto	" Rule length (per Table 22) size <u>—</u>
Frames <u>"</u>	Have Watertight Doors now been examined and found efficient? <u>—</u>	Ditto ditto at other places ditto	Hawsers & Warps <u>Good</u>
Reverse Frames <u>"</u>	Have Watertight Doors now been examined and found efficient? <u>—</u>	Stringers, Clamps & Shells ditto	Standing & Running Rigging <u>"</u>
Floors <u>"</u>	Have Watertight Doors now been examined and found efficient? <u>—</u>	Salting (State if examined.) ditto	
Keelsons <u>"</u>	Have Watertight Doors now been examined and found efficient? <u>—</u>	Copper, or Y.M. (State if on Felt.) ditto	
	Dblg. Plates under Sounding Pipes <u>—</u>	When put on, Month Year	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel now appears to be in good efficient condition & in my opinion, eligible to remain as classed without fresh record of survey.

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,
Survey Fee (per Section 28)	£	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18
Second Surveyor's Fee (if any)	£	

Committee's Minute

Character assigned

FRI. 10 MAR 1899

As now
without spl. cond.

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

LON 717-0481