

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18th May 1899 When handed in at Local Office 18 Port of London
No. in Survey held at London Date, First Survey 2nd May 1899 Last Survey 8th May 1899
Reg. Book 400 on the Wood, Iron or Steel S.S. Cayo Romano Master J. Readhead & Son

TONNAGE:— Built at S. Shields By whom J. Readhead & Son When 1893.9
GROSS 2640 Owners E. Bigland & Co. Port belonging to London
UNDER DEK. 2523 Owners' Address (if not already recorded in Appendix to Register Book.)
NET 1715

Surveyed Afloat or in Dry Dock? 9.7K Name of Dock Burns Destined Voyage
WB=CellDBorDBa feet; uE&B feet; J feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 59926 Port London
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER. 101A1 2.M.C.S.98
Date of last Survey and of Periodical Surveys. Sparks 5.98
S.S. London 5.98

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition, Damage through Striking the
Dun at St. Orleans on 20th March/99. and Striking a Buoy at Port
Royal on the 1st March/99.

Steel and bottom examined in dry
dock, two rivets removed at upper part of aperture, and edge of
plate recandked, three rivets removed in upper part of middle, four
rivets caulked in way of port coal bunker, and a Lap rivet fitted
on Star^d side at after part of after hold. Bottom cleaned
and recrated.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks <u>Good</u>	Inner Bottom Plating <u>Good</u>	Coal Bunkers, Open'gs, Lids, &c. <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Caulking of Decks <u>Good</u>	State if Tanks now tested <u>Good</u>	Scuppers <u>Good</u>	Condition, how ascertained <u>from 8th</u>
Waterways <u>Good</u>	Bulkheads <u>Good</u>	Cargo Hatchways <u>Good</u>	(State if wedges removed <u>no</u>)
Coamings <u>Good</u>	Ceiling <u>Good</u>	Hatches <u>Good</u>	Sails <u>Good</u>
Beams & Fastenings <u>Good</u>	Cement or Asphalt (State which.) <u>Good</u>	Planking of Wood Vessels <u>Good</u>	Equipment letter <u>u</u>
Outside Plating <u>Good</u>	Rudder <u>Good</u>	Treenails ditto <u>Good</u>	Anchors, No. of <u>3 B. 15. 1K</u>
Caulking of ditto <u>Good</u>	Windlass <u>Good</u>	Breasthooks & Stemson ditto <u>Good</u>	Cables (State if now ranged) <u>u</u>
Rivets <u>Good</u>	Have Pumps now been examined and found efficient? <u>Good</u>	Transoms, Pointers, & Crutches ditto <u>Good</u>	" length size (on board) <u>Good</u>
Breasthooks & Crutches <u>Good</u>	Have Sluice Valves now been examined and found efficient? <u>Good</u>	Timbers of Frame at openings ditto <u>Good</u>	" Rule length size (per Table 22) <u>Good</u>
Transoms <u>Good</u>	Have Watertight Doors now been examined and found efficient? <u>Good</u>	Ditto ditto at other places ditto <u>Good</u>	Hawsers & Warps <u>Good</u>
Frames <u>Good</u>	Have Watertight Doors now been examined and found efficient? <u>Good</u>	Stringers, Clamps & Shells ditto <u>Good</u>	Standing & Running Rigging <u>Good</u>
Reverse Frames <u>Good</u>	Windlass <u>Good</u>	Salting (State if examined.) ditto <u>Good</u>	
Floors <u>Good</u>	Have Pumps now been examined and found efficient? <u>Good</u>	Copper, or Y.M. (State if on felt.) ditto <u>Good</u>	
Keelsons <u>Good</u>	Have Sluice Valves now been examined and found efficient? <u>Good</u>	When put on, Month Year <u>Good</u>	
	Dblng. Plates under Sounding Pipes <u>Good</u>		

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."
This vessel is now in good and
efficient condition, and eligible to remain as Classed
with record 5.99.

Office Fee (if chargeable) per Scale II., Sec. 27£
Survey Fee (per Section 28)£
Special Damage or Repair Fee (if any)£
Travelling Expenses (if chargeable)£
Second Surveyor's Fee (if any)£
Fees applied for,18.....
Received by me,18.....
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character assigned
FRI. 19 MAY 1899
10001
Sparks
Lloyd's Register Foundation
© 2019
Lloyd's Register Foundation
LON 718 - 0239