

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18. When handed in at Local Office 18. Port of London
No. in Survey held at London Date, First Survey 12-6-92 Last Survey 22-6-99
Reg. Book. 6 on the Wood, Iron or Steel S.S. "Dabulamangi" (No. of Visits) Master ✓

TONNAGE:— Built at Aberdeen By whom Hall Russell & Co. When 1882-5
GROSS 1537 Owners J. T. Pennie & Son Port belonging to Aberdeen
UNDER DE. 998 Owners' Address
NET 980 (If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Union Dry Dock Destined Voyage -

WB=CellDBorDBa feet; uE&B feet; J feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 1507 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Buoys is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Special Survey No. 1. Part in anticipation

Vessel placed in dry dock, bottom keel stern frame and rudder examined, cleaned and coated.

Double bottom under boilers examined inside and efficiently repaired as follows. Viz—
Side girders under Main boilers, ^{found, washed now} doubled with 7/16 iron plates in 4 spaces on starboard side and 3 spaces on the port side, cement made good.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								
PRESENT CONDITION OF THE	Good	Good	Good	Good	Good	Good	Good	Good
Decks	Good	Good	Good	Good	Good	Good	Good	Good
Caulking of Decks	✓	✓	✓	✓	✓	✓	✓	✓
Waterways	✓	✓	✓	✓	✓	✓	✓	✓
Coamings	✓	✓	✓	✓	✓	✓	✓	✓
Beams & Fastenings	✓	✓	✓	✓	✓	✓	✓	✓
Outside Plating	✓	✓	✓	✓	✓	✓	✓	✓
Caulking of ditto	✓	✓	✓	✓	✓	✓	✓	✓
Rivets	✓	✓	✓	✓	✓	✓	✓	✓
Breasthooks & Crutches	✓	✓	✓	✓	✓	✓	✓	✓
Transoms	✓	✓	✓	✓	✓	✓	✓	✓
Frames	✓	✓	✓	✓	✓	✓	✓	✓
Reverse Frames	✓	✓	✓	✓	✓	✓	✓	✓
Floors	✓	✓	✓	✓	✓	✓	✓	✓
Keelsons	✓	✓	✓	✓	✓	✓	✓	✓
Stringers	✓	✓	✓	✓	✓	✓	✓	✓
Inner Bottom Plating	✓	✓	✓	✓	✓	✓	✓	✓
State if Tanks now tested	✓	✓	✓	✓	✓	✓	✓	✓
Bulkheads	✓	✓	✓	✓	✓	✓	✓	✓
Ceiling	✓	✓	✓	✓	✓	✓	✓	✓
Cement or Asphalt (State which.)	✓	✓	✓	✓	✓	✓	✓	✓
Rudder	✓	✓	✓	✓	✓	✓	✓	✓
Windlass	✓	✓	✓	✓	✓	✓	✓	✓
Have Pumps now been examined and found efficient?	✓	✓	✓	✓	✓	✓	✓	✓
Have Sluice Valves now been examined and found efficient?	✓	✓	✓	✓	✓	✓	✓	✓
Have Watertight Doors now been examined and found efficient?	✓	✓	✓	✓	✓	✓	✓	✓
Dblg. Plates under Sounding Pipes	✓	✓	✓	✓	✓	✓	✓	✓
Engine Room Skylights	✓	✓	✓	✓	✓	✓	✓	✓
Coal Bunkers, Open'gs, Lids, &c.	✓	✓	✓	✓	✓	✓	✓	✓
Scuppers	✓	✓	✓	✓	✓	✓	✓	✓
Cargo Hatchways	✓	✓	✓	✓	✓	✓	✓	✓
Hatches	✓	✓	✓	✓	✓	✓	✓	✓
Planking of Wood Vessels	✓	✓	✓	✓	✓	✓	✓	✓
Treenails	✓	✓	✓	✓	✓	✓	✓	✓
Breasthooks & Stemson	✓	✓	✓	✓	✓	✓	✓	✓
Transoms, Pointers, & Crutches ditto	✓	✓	✓	✓	✓	✓	✓	✓
Timbers of Frame at openings ditto	✓	✓	✓	✓	✓	✓	✓	✓
Ditto ditto at other places ditto	✓	✓	✓	✓	✓	✓	✓	✓
Stringers, Clamps & Shells	✓	✓	✓	✓	✓	✓	✓	✓
Salting (State if examined.)	✓	✓	✓	✓	✓	✓	✓	✓
Copper, or Y.M. (State if on felt.)	✓	✓	✓	✓	✓	✓	✓	✓
When put on, Month	✓	✓	✓	✓	✓	✓	✓	✓
Year	✓	✓	✓	✓	✓	✓	✓	✓
Boats	✓	✓	✓	✓	✓	✓	✓	✓
Masts, Yards, &c.	✓	✓	✓	✓	✓	✓	✓	✓
Condition, how ascertained	✓	✓	✓	✓	✓	✓	✓	✓
(State if wedges removed)	✓	✓	✓	✓	✓	✓	✓	✓
Sails	✓	✓	✓	✓	✓	✓	✓	✓
Equipment letter	✓	✓	✓	✓	✓	✓	✓	✓
Anchors, No. of	✓	✓	✓	✓	✓	✓	✓	✓
Cables (State if now ranged)	✓	✓	✓	✓	✓	✓	✓	✓
length (on board)	✓	✓	✓	✓	✓	✓	✓	✓
Rule length (per Table 22)	✓	✓	✓	✓	✓	✓	✓	✓
Hawsers & Warps	✓	✓	✓	✓	✓	✓	✓	✓
Standing & Running Rigging	✓	✓	✓	✓	✓	✓	✓	✓

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel being now in a good and efficient condition is eligible in my opinion to remain as classed, to be credited with examination of bottom outside & the interior of double bottom in S.B.B. Space as part of S.S. No. 1 and to have record of Survey 6.99.

Office Fee (if chargeable) per Scale II, Sec. 27	£	:	:	Fees applied for,
Survey Fee (per Section 28)	£	:	:	18.
Special Damage or Repair Fee (if any) (per Sec. 28)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18.
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British & Foreign Shipping.

J. Shilston

FRI. 26 JUL 1899

TUES. 19 JUN 1900

© 2019

Lloyd's Register Foundation