

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office.

TUES. 8 AUG 1899

Date of writing Report *7 Aug 99* When handed in at Local Office *7 Aug 99* Port of *London*
No. in Reg. Book *120* Survey held at *London* Date, First Survey *1 Aug 98* Last Survey *3 Aug 1899*
on the Machinery of the Wood, Iron or Steel Master *T. T. Adjutant*
Gross Tonnage *2392* Net *1532* Vessel built at *W. H. H. H.* By whom *H. Gray & Co. Ltd* When *1893* YEAR. MONTH. *6*
Registered Horse Power *2* Engines made at *"* When *93* Boilers, when made (Main) *93* (Donkey) *93*
No. of Main Boilers *1* Owners *Gen. H. H. H. H.* Port *London* Voyage *Genoa*
No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Official Mr. Mill Hole Pier*
Main Boilers *1* Donkey Boilers *1*

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER. *For Special Survey.* Date of last Survey and of Periodical Surveys. *11.98. + L.M.E. + 100A. 11.98.* Year Assigned for next survey. *1899.* Machinery and Boiler Surveys (including date of N.B., if any). *1898-10-98. B.S. 2.98.*

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *yes.*
Do. " Donkey " " " *no*
If this was not done, state for what reasons? *Latter at work.*
What parts of the Boilers could not be thus thoroughly examined?
What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
Did the Surveyor examine the Safety Valves of the Main Boiler? *yes.* To what pressure were they afterwards adjusted under steam? *Not adj'd*
Did the Surveyor examine the Safety Valves of Donkey Boiler? *no* To what pressure were they afterwards adjusted under steam? *"*
Has the propeller shaft been drawn and examined at this time? *no* If spare propeller shaft fitted, state whether new?
What is the distance between the nut of stern bush and top of after bearing of screw shaft?

The Survey is not complete state what arrangements have been made for its completion and what remains to be done?
On vessel's return from Genoa:- Donkey Boiler and its Safety Valves to be examined and all Safety Valves adjusted under steam. Owners advised.
Now done: Main Boilers examined throughout and found to be generally in good order.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, B.&M.S. 9,97 or L.M.C. 9,97, 140 lb., &c.)

The Machinery of this vessel as now seen is in good order and, in my opinion, eligible to remain as classed with fresh record of + L.M.E. B.S.-8'99. When this survey is completed.

Fee or Registration Fee (per Sec. 27) *£ 2*
Survey Fee (per Section 28) *£ 2*
Total Damage Fee (per Section 28) *£ 4*
Voyelling Expenses (if chargeable) *£ 1.16*
Fees applied for *8/8 1899*
Received by me, *25/8 1899*

D. Ritchie
TUES. 23 JAN 1900
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute *FRID. 11 AUG 1899*
Signed *Deferred*
Rpt to Ind. 24/10/99
Deferred (on return)
White Own
20.31/10/99
Deferred
White Own
20.24/11/99
Lloyd's Register Foundation

13th Dec 89 to be completed on the vessel
return from Genoa.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that this
vessel WILL BE eligible for
the record.

13th Dec 89 when the
monkey baller and the safety
valves have been examined
and all safety valves
adjusted and tested.

Emm. A.
8/8/99

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation