

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report Sept-15th 99 When handed in at Local Office 18 Port of London SEP 16 1899

No. in Reg. Book. 418 Survey held at London Date, First Survey and Last Survey Sept-12th 1899

on the Machinery of the Wood, Iron or Steel S.S. "Guitagel Castle" Master Haris

Tonnage { Gross 3537 Net 3542 Vessel built at Gr. By whom Fairfield & Co. Ld. When 1896 Boilers when made (Main) 1896 (Donkey) —

Registered Horse Power 620 Engines made at Gr. Owners (S. Currier & Co.) Port London Voyage Natal

No. of Main Boilers 4 If Surveyed in Dry Dock James L. Dry Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

No. of Donkey Boilers 0 Steam Pressure 170 lb. in Main Boilers 0 in Donkey Boilers 0

Last Survey No. — Port —Particulars of Examination and Repairs (if any) Donkey

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Examined propeller, Stern bush, & Sea connections fastenings, found same all in good condition.

Completed.

General Observations, Opinion, and Recommendation:

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, B.&M.S. 9,97 or L.M.C. 9,97, 140 lb., F.D., &c.)

This vessel's Machinery is
now as far as seen in good condition & in my opinion the
vessel is eligible to remain as classed.

Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	:	:	18
Special Damage Fee (per Section 28)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18

State if Certificate is required

Committee's Minute

TUES. 19 SEP 1899

Assigned

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



Lloyd's Register Foundation

Lan 719 - 0272

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

*It is submitted that
this vessel is eligible to
remain as CLASSED.*

LL
16/9/99

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation