

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

WED 11 OCT 1899

Date of writing Report October 10th 1899 When handed in at Local Office

No. in Reg. Book Survey held at Tilbury

150 on the Machinery of the Wood, Iron or Steel Iwin S.S. Orrah

Gross 5291.

Net 4632

Registered 1772

Horse Power 5

No. of Main Boilers

No. of Donkey Boilers 1

Steam Pressure in Main Boilers 150 ft

in Donkey Boilers 120 ft

Vessel built at 91s

Engines made at 50

Owners Orient P. Nav. Co. Ltd

If Surveyed Afloat or in Dry Dock Tilbury Dry D.

(State name of Dock.)

Date, First Survey and

By whom Fairfield Co. Ld.

When 1899

Boilers, when made (Main) 1899

(Donkey) 1899

Port Glasgow

Voyage Australia

Port of London.

Last Survey October 6th 1899

Master Fulton

(No. of Visits 1)

YEAR. MONTH.

When 1899 1

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
X for Special Survey.Date of last Survey and of
Periodical Surveys.

F 100 A. 1. 6. 99.

Years Assigned now
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).

Last Survey No. Port

Particulars of Examination and Repairs (if any) Docking.

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.

"

Donkey "

"

"

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

91s
91o
91o

Did the Surveyor examine the Safety Valves of Donkey Boiler?

91o

Has the propeller shaft been drawn and examined at this time?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Examined propellers, stern bushes, and sea connections/fastenings, found same all in good condition.

F 100 A. 1. 6. 99.

F 100 C. 1. 99.

General Observations, Opinion, and Recommendation:—This vessel's machinery is

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressure, &c.: thus, for example, B.S. 0,97, B.&M.S. 0,97 or X.L.M.C. 0,97, 140 lb. F.D., &c.)

now as far as seen in good condition & in my opinion the vessel is eligible to remain as classed

Office or Registration Fee (per Sec. 27).....

2

Fee applied for

Survey Fee (per Section 28).....

2

10

Special Damage Fee (per Section 28).....

2

Received by me,

Travelling Expenses (if chargeable).....

2

10

R.M. Salma.

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute

FRID 13 OCT 1899

Assigned

As now



© 2019

Lloyd's Register
Foundation

LON719-0375

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

To copy
this report
remain as
J.L. SELL

AMBD.
11/10/99

• THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation