

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18 Port of London
 No. in Survey held at London Date, First Survey 12/9/98 Last Survey 30/10/99
 Reg. Book 351 on the Wood, Iron or Steel Comp S. Torrens Master James

TONNAGE:— Built at Sunderland By whom J. Lawie When 1895 MONTH 10
 GROSS 1333 Owners A. H. Alder & Co. (Mgs) Port belonging to London
 UNDER DE. 1098 Owners' Address (if not already recorded in Appendix to Register Book.)
 NET 1198

Surveyed Afloat or in Dry Dock? Yes Name of Dock Price's Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }
 total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 302 Port Adel

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage: (After collision with iceberg).

This vessel has now been placed in dry dock, the yellow metal sheathing stripped off the bottom, the vessel re-caulked from keel over all including decks & the bottom re-sheathed with yellow metal on felt.

Repairs to damage to the bonplanking - 11 bon shifts on each side - the result of collision with an iceberg on the outward passage were done in Adelaide, but being of Corrie pine and badly shifted and fastened with plain iron bolts have now been renewed of teak to the original shifts and fastened with galvanized iron bolts.

The head knee figure head together with the head rails & flights have now been renewed and the house pipes taken out & refitted, the harrow boys being renewed. One frame on the port bow has been fitted with brass piece.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks <u>Good</u>	<u>Good</u>		<u>Good</u>
Caulking of Decks <u>"</u>	Inner Bottom Plating <u>Good</u>	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Waterways <u>"</u>	State if Tanks now tested	Scuppers <u>Good</u>	Condition, how ascertained <u>from dk</u>
Coamings <u>"</u>	Bulkheads	Cargo Hatchways	(State if wedges removed)
Beams & Fastenings <u>"</u>	Ceiling <u>Good</u>	Hatches <u>Comp.</u>	Sails <u>Good</u>
Outside Plating <u>"</u>	Cement or Asphalt (State which.)	Planking of Wood Vessels	Equipment letter <u>18</u>
Caulking of ditto <u>"</u>	Rudder	Treenails ditto	Anchors, No. of <u>36, 15, 24</u>
Rivets <u>"</u>	Windlass	Breasthooks & Stemson ditto	Cables (State if now ranged)
Breasthooks & Crutches <u>"</u>	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length <u>not now</u>
Transoms <u>"</u>	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	(on board) <u>size</u>
Frames <u>"</u>	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	" Rule length <u>ranged</u>
Reverse Frames <u>"</u>		Stringers, Clamps & Shelves ditto	(per Table 22)
Floors <u>not can</u>	Have Watertight Doors now been examined and found efficient?	Salting (State if examined.) ditto <u>Y. manifest</u>	Hawsers & Warps <u>Good</u>
Keelsons <u>gd.</u>	Dblng. Plates under Sounding Pipes	Copper, or Y.M. (State if on felt.) ditto <u>Y. manifest</u>	Standing & Running Rigging
		When put on, Month <u>Oct</u> Year <u>1999</u>	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel now appears to be in good condition and is eligible in my opinion to remain as classed with fresh record surveying 10,99 Lon.

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,
Survey Fee (per Section 25)	£	18
Special Damage or Repair Fee (if any) (per Sec. 26.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18
Second Surveyor's Fee (if any)	£	

Committee's Minute

Character assigned

FRI. 10 NOV 1899

Cont 12 A1

J. H. M. 10.99

Surveyor to Lloyd's Register of British & Foreign Shipping.

Lloyd's Register Foundation

LON720-0010