

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 24/11/99 When handed in at Local Office 18 Port of London
 No. in Reg. Book 613 Survey held at London Date, First Survey 17/10/99 Last Survey 29/10/99
 on the Wood, Iron or Steel S.S. Guillemet Master CRB
 TONNAGE:— Built at Campbelltown By whom Campbell When 1894
 GROSS 1771 Owners General Steam Nav. Co. Port belonging to London
 UNDER DECK 1331 Owners' Address
 NET 1134 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Yes Name of Dock Beaufort Green Destined Voyage Mediterranean

WB=CellDBorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted
 total capacity tons. FPT tons; APT tons; MT tons. } precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 61500 Port London

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

CHARACTER.
 for Special Survey.
 Date of last Survey and of Periodical Surveys.
 Years and how expired.
 Machinery and Boiler Surveys (including date of N.B., if any).
+100 A1
pt along dk
with freeboard.
S.S. hon N.P. 99
10,99
 Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage (alleged collision with S.S. Beneficent & touching ground)

The rudder which was found to be twisted was removed, placed in the fire and trued, and replaced.

The paint on the bottom was found to be abraded, and in way of the after ballast tank there was found a slight leak at lower edge of B. strake. This was caulked. The vessel was partly laden so no opportunity was found to examine the tank internally to ascertain the state of the cement etc., or to test it. This is to be done on the vessel's return.

The port house pipe has been renewed, and one stem plate and one doubting plate in way of same have been renewed. One bul-

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed	3							Hawsepipes, etc
Removed and Fair'd or Repaired								
Fair'd or Repaired in place	2							

PRESENT CONDITION OF THE	Stringers	Engine Room Skylights	Boats
Decks	Inner Bottom Plating	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Caulking of Decks	State if Tanks now tested	Scuppers	Condition, how ascertained
Waterways	Bulkheads	Cargo Hatchways	(State if wedges removed)
Coamings	Ceilings	Hatches	Sails
Beams & Fastenings	Cement or Asphalt (State which.)	Planking of Wood Vessels	Equipment letter
Outside Plating	Rudder	Treenails ditto	Anchors, No. of
Caulking of ditto	Windlass	Breasthooks & Stems ditto	Cables (State if now ranged)
Rivets	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length size (on board)
Breasthooks & Crutches	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" Rule length size (per Table 22)
Transoms	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Hawsers & Warps
Frames	Have Watertight Doors now been examined and found efficient?	Salting (State if examined.) ditto	Standing & Running Rigging
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Copper, or Y.M. (State if on felt.) ditto	
Floors	Dblg. Plates under Sounding Pipes	When put on, Month Year	
Keelsons			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel appears to be in good condition and is eligible in my opinion to remain as classed without fresh record of survey.

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,
Survey Fee (per Section 28)	£	18.
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18.
Second Surveyor's Fee (if any)	£	

Committee's Minute
 Character assigned

TUES. 28 NOV 1899

TUES. 9 JAN 1900

Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
 Foundation

LON720-0108

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

61666. Jan.
- bark stem plate has been renewed and one plate on each side fairied in place. The bulk moulding on bulwark top has been removed, fairied & replaced and three stanchions removed fairied & replaced. Jollyboat repaired.

C.M.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation