

267 Enr  
1825

Chieftain

See Std 450 & Stk 49 Lloyd's Register

\*1624

Of British and Foreign Shipping.

Sunderland, 25 April 1840

Cleveland  
Velocity  
Wm. Lushington

Mr. Charles Graham Esq.  
Sir

We duly received your letter of the 18<sup>th</sup> Inst.  
and in reply there to say the name of the new Ship  
No 1613 is the "Tone" -

The name of No 1121 "Oria" is removed that the  
Fictitious fastenings according to the Rule is required and  
with which we doubt not he will comply

The sum referred to we receive and will be  
accounted for in our next remittance

In view of Ships Agnes - Vise and Britannia  
now sent Queen to our usual time of sending the Repairs  
are desirous of having the Charter assigned to those Vessels  
as early as possible and a Certificate thereof forwarded  
them to this office as they cannot get their insurance effected  
until they actually produce such documents.

From the very slender repair which the Chieftain  
Letter Book is receiving since our letter of the 3<sup>rd</sup> Inst. we are again induced  
to ask the Committee to reconsider the matter; and decide  
whether under all the circumstances of the case the Agent should  
be allowed to proceed.

SUB926-0022112

not come under the operation of the First Rule for restoration: observing that as nearly as possible, the Second Rule is in fact complied with: we give you the description of repair which will bear on our Statement: and so far to prove that the Vessel is receiving more than is required even by the Second Rule..

10 plow Timber. 17 of 2<sup>d</sup> port holes, 2 of 1<sup>d</sup> port holes.  
35 of new 3 port holes and Top timber and staves  
the Timber alst put in of old but sound material  
new Knight Rd. on the S Side: new Hawse Timber on both sides  
2 new Breast ports and the others rebotted; new Apes & bottom;  
one half new Hull Beams; and latter have fastenings to the  
whole of the beams

2/3<sup>d</sup> new Deck Beams and latter have fastenings aloft.

Latter new Waterways - Bulk - Hatch Stays. New  
Strakes - Topside and Black Strakes; several new Planks  
in the hold, and below the water when the Slightest  
leak penetration itself is new outside planks from the  
Floor Rd to the 1<sup>d</sup> port hole head on midship or both sides.

New Hull Plates - Painter pieces and Hatch after.

Latter new ceiling except a few planks in the deckhouse -

The variation a departure from the 2<sup>d</sup> Rule is that the whole of the outside  
plank is not stripped off down to the 2<sup>d</sup> port hole head: but in lieu  
thereof the latter ceiling is renewed or nearly so: besides a very large  
portion of the former (outside plank); and that which is left on is  
inspected sound & good, and some of it very recently put on. We therefore  
think the Committee can with perfect safety permit this Vessel  
to be restored to the first class for such number of years as our

Report may warrant us in recommending when the repairs are  
fully completed -

It appears as the Vessel would only be entitled to 8 years -  
had she been the Second Rule; on account only of the Elm & Birch  
strake being carried up to the light water mark: that is the Rule -  
but we think it ought to be remembered that this ship was built  
in the absence of all Rules, and long before the existence of the  
present Arbitration: which is our opinion given the present some claim  
below the case demanded: besides the very large expense he is going  
to incur, which will be found in the annexed description of the Repair.

We are much aware to give you either yourself or the  
Committee any other a unnecessary trouble, but feel this to  
be a case that requires us in the discharge of our duty,  
to draw the particular attention and consideration of the  
Committee themselves to all the circumstances attending it.

And remain Sir

Your ob<sup>t</sup> Servt

B. Wm. D. Slaney -



Charles Graham Esq

Lloyd's Register Office

London



© 2021  
Lloyd's Register  
Foundation