

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

23 MAY 1949

Date of writing Report 25th April 1949. When handed in at Local Office 26th April 1949 Port of HALIFAX, N. S.
 in Survey held at Liverpool, N. S. Date, First Survey 3rd March Last Survey 6th April, 1949.
 Book on the Machinery of the ~~Wood-Deane~~ Steel Single Screw Steamer "ELKHOUND" (No. of Visits Two)

Age { Gross 729 Vessel built at Bristol By whom G. Hill & Sons, Ltd. Year. Month.
 Net 301 Engines made at Clydebank By whom Aitchison, Blair, Ltd. When 1929 - 10
 106 M.N. Boilers, when made (Main) 1934 - 9 (Donkey) When 1934 - 9
 of Main Boilers 1 S.B. Owners Irving Steamships, Ltd. Owners' Address.

Donkey Boilers None Managers. -- Port St. John, N. E. Voyage --
 Pressure 180 lbs. If Surveyed Afloat or in Dry Dock Afloat at Liverpool, (State name of Dock.)
 Donkey Boilers --

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Report No. 5780 Port B. S.

Particulars of Examination and Repairs (if any) B. S.
 Medical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on the cause of which must be stated should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Image cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey " " " "

was not done, state for what reasons?

what parts of the Boilers could not be thus thoroughly examined? All parts examined.

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

latest date of internal examination of each boiler Main boiler 3-3-49 Present condition of funnel(s) Good

the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 180 lbs./sq.in.

the Surveyor examine the Safety Valves of Donkey Boiler? -- To what pressure were they afterwards adjusted under steam? --

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers? --

the Surveyor examine the drain plugs of the Main Boilers? --, and of the Donkey Boilers? --

the Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boilers? --

screw shaft now been drawn and examined? No Is it fitted with continuous liner? -- Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? --

shaft now been changed? -- If so, state reasons --

the shaft now fitted been previously used? Has it a continuous liner? -- Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? --

date of examination of Screw Shaft State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft --

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted? Yes

did the Surveyor examine the generators, motors, switchgear, cables and fuses? No

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? No

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

W DONE The main boiler examined internally and externally together with all mountings, and

and or placed in good order. Safety valves subsequently adjusted under steam to 180 lbs. per sq.

W. P. The oil fuel and steam smothering installation generally examined and tested under work-

conditions and found satisfactory.

PAIRS (Wear & Tear):-

New valve spindles fitted in main feed check valve, blow-down valve, and O. F. unit steam

op valve.

General Observations, Opinion, and Recommendation:- The Machinery of this vessel is eligible in

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.E.M.S. 9,11, L.M.C. 9,11, or

* LMC 140 lb., F.D., &c.) CS 3,34,

opinion to remain as classed, with fresh record of B. S. 4,49.

Survey Fee (per Section 29) \$40.00 Fees applied for

Special Damage or Repair Fee (if any) £ : : Apr. 21 1949

(per Section 29.)

Travelling expenses (if chargeable) \$10.00 Received by me, 19

Committee's Minute TUES. 31 MAY 1949

Assigned OS 4,49

Acting Engineer Surveyor to Lloyd's Register of Shipping.

© 2020

Lloyd's Register Foundation

W1000-0029