

Rpt. 8.

WRECK SECTION

No. 569

(Received at London Office)

No. 2167

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 16/11/48 When handed in at Local Office 16/11/48 Port of Gdynia
No. in Survey held at Gdynia Date, First Survey 9.11.48 Last Survey 12.11.1948
Reg. Book. on the Wood/Iron/Steel S.S. "KATOWICE" (No. of Visits two)
64609 Built at Gdynia By whom Chant. Nav. Francals When 1925 10

TONNAGE :-
GROSS 1995
UNDER DK. 1553
NET 1107

Owners Zegluga Polska S.A. Owners' Address -
Managers Gdynia-America Shipping Lines Ltd. Port belonging to Gdynia Szczecin
Destined Voyage -

Surveyed Afloat or in Dry Dock? afloat Name of Dock Gdynia
Cell/Bor/DBa - feet; uE & B - feet; f - feet
total capacity - tons. FPT - tons; APT - tons; MT - feet - tons.
Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 25004 Port ANT

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Issue of Seaworthy Certificate and Damage Repairs.

Now done:- Examined the rudder as far as possible and rudder quadrant and found in good order. The Owners representative states that the vessel will be drydocked in January 1949, when the new rudder, now being constructed, will be fitted. An Interim Certificate, copy herewith, was issued.

Damage Repairs:- Damage stated to have occurred on the 23rd and 24th October 1948 during heavy weather whilst on a voyage from Gdansk to Ghent.

New manilla ropes and one triple sheave block fitted to auxiliary steering gear tackles

8 scuttle glasses renewed

3 " glass frames "

1 deadlight "

Other minor repairs effected.

The Owners representative stated that the following repairs and replacements were effected when the vessel arrived at Ghent and that a Damage Report was made by Mr. Gaston Labaye, but there is no evidence that any of the Society's Surveyors were called in.

Fore peak air pipe repaired

One new tarpaulin fitted to No. 1 hatch

" " " " 2 "

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...	///	///	///	///	///	///	///	///
Removed and Faird or Repaired								
Faird or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats Above Items
Beams & Fastenings SURVEY	Rudder CONFINED	Scuppers TO THE	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged.)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board.)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Have the Tanks been examined internally?	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Have the Tanks been tested?	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
		Salting State if examined.	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel as far as now seen, is in an efficient condition and eligible in my opinion to remain as classed without fresh record of survey, subject to the rudder being renewed before the end of March 1949 and to all the other items at present attached to the vessel's Class being dealt with as previously recommended.

Survey Fee (per Section 29) £ : --- :
Special Damage or Repair Fee (if any) (per Sec. 29) £1.10.000 :
Travelling Expenses (if chargeable) £1. : 450 :
Second Surveyor's Fee (if any) £ : : :

Fees applied for, 16/11/48

Received by me, not yet 19

Committee's Minute

Character Assigned

FRI. 17 DEC. 1948

As now, subject

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register Foundation