

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

2 JUN 1942

Date of writing Report \_\_\_\_\_ When handed in at Local Office 1/6/1942 Port of NEWCASTLE-on-Tyne  
 No. in Reg. Book. 25373 Survey held at South Shields Date, First Survey May 11 Last Survey May 21 1942  
 on the Machinery of the Wood, Iron or Steel S.S. HOPESTAR (No. of Visits 2)

Tonnage { Gross 5267 Vessel built at Newcastle By whom Swan Hunter & Wigham & Co. Ltd. When 1936-2  
 Net 3192 Engines made at Wallend By whom Parsons Marine Steam Turbine Co. Ltd When 1936  
 Nominal Horse Power { 400 Boilers, when made (Main) 1936 (Donkey) 1936  
 No. of Main Boilers 2 Owners Wallend Shipping Co. Ltd Owners' Address \_\_\_\_\_  
 No. of Donkey Boilers 1 Managers Stott, Mann, Fleming & Co. Ltd (if not already recorded in Appendix to Register Book.)  
 Steam Pressure in Main Boilers 285 If Surveyed Afloat or in Dry Dock At Sea Port Newcastle Voyage \_\_\_\_\_  
 in Donkey Boilers 120 (State name of Dock.) Reedheads & Garrow

Last Report No. \_\_\_\_\_ Port \_\_\_\_\_  
 Particulars of Examination and Repairs (if any) B.S.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey " " " Under steam

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler 11-5-42 Present condition of funnel(s) efficient

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓, and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓, and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? ✓ Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft ✓ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 5/32

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms.?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Main boiler mountings & safety valves to examine & their safety valves to adjust. Donkey boiler to examine in its entirety & its safety valves to adjust.

Propeller, sea connections & outside fastenings examined & found in order. Main boilers examined internally & externally & placed in safe working condition.

Repairs. Several cracks in back c.c. plates in way of rivets cut out, built up & new rivets. 1 stay tube renewed in starboard boiler. 1 new superheater element & 2 connecting pipes renewed. Several old superheater elements renewed.

The Owners Representative states the survey will be completed first opportunity.

General Observations, Opinion, and Recommendation:— The machinery of this vessel is eligible in my opinion to remain as classed & to have record of B.S. 5, 42 when the survey is complete.

Yam R. is attached Rpt. 8.

Survey Fee (per Section 29) £ 4 : 0 : 0 Fees applied for 17 JUN 1942  
 Special Damage or Repair Fee (if any) £ \_\_\_\_\_  
 Travelling expenses (if chargeable) £ \_\_\_\_\_  
 Received by me, J. H. Waterhouse

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUE 30 JUN 1942  
 Assigned As now



Insert Character of Ship and Machinery previously as in the Register Book

If so, to be sent to

Pro du 842 New parts held

It is submitted that this vessel WILL BE eligible for the records.

Pro 542 on

Completion

Plus

296.42

*[Faint handwritten text, likely bleed-through from the reverse side of the page]*



© 2020

Lloyd's Register Foundation