

No. in  
Reg. Book. 76170 Survey held at Newcastle Date, First Survey 23/9/38 Last Survey 4<sup>th</sup> Oct 1938  
on the Machinery of the ~~Wood, Iron or Steel~~ s/s "HOPESTAR" (No. of Visits 6)

tonnage) Gross <u>526 1/2</u>	Vessel built at <u>Newcastle</u>	By whom <u>Ivan, Hunter &amp; Wigan Richard &amp; Co</u>	When <u>1936-2</u>
Net <u>3192</u>	Engines made at <u>"</u>	By whom <u>Parsons Marine Eng</u>	When <u>1936</u>
Nominal Horse Power <u>400</u>	Boilers, when made (Main) <u>1936</u>	(Donkey) <u>✓</u>	<u>Furb. &amp; Co</u>
No. of Main Boilers <u>258</u>	Owners <u>Wallaseed Shipping Co. Ltd</u>	Owners' Address <u>Manchester</u>	
No. of Donkey Boilers <u>1</u>	Managers <u>Arthur Stott &amp; Co</u>	(If not already recorded in Appendix to Register Book.)	
Steam Pressure— <u>285 lb</u>	Port <u>Newcastle</u>	Voyage	
In Main Boilers	Surveyed Afloat or in Dry Dock <u>Ivan Hunter &amp;</u>	Particulars of Classification (which must be inserted)	
In Donkey Boilers <u>120 lb</u>	(State name of Dock.) <u>Wigan Richard &amp; Co</u>		

Particulars of Examination and Repairs (if any)	Date of last Survey and of Periodical Surveys.	Year of last Survey and of Periodical Surveys.	Surveys (including date of N.B., if any).
DKg. & new Propeller	+100 A1		+1 MC 23

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *Yes*

" " Donkey " "

als was not done, state for what reasons? Rebels not due for survey.

What parts of the Boilers could not be thus thoroughly examined? .....

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

the latest date of internal examination of each boiler .....

the Surveyor examine the Safety Valves of the Main Boiler? Yes (at Glasgow) To what pressure were they afterwards adjusted under steam? 285 lbs

the Surveyor examine the Safety Valves of Donkey Boiler ? ..... To what pressure were they afterwards adjusted under steam ? ✓

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ☒ , and of the Donkey Boilers? ☒

the Surveyor examine the drain plugs of the Main Boilers? ☒ ..... and of the Donkey Boiler? ☒

the Surveyor examine all the mountings of the Main Boilers? ☒ and of the Donkey Boiler? ☒

screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

shaft now been changed? no If so, state reasons ✓

the shaft now fitted been previously used? ☒ Has it a continuous liner? ☐ Is an approved appliance fitted at the after end of )

State the date of examination of Screw Shaft 26/9/38 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 3/32"

Engine parts, when referred to by numbers, should be counted from forward.

e Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Now done: Vessel placed in dry dock. Propeller, stern bush, screw shaft (drawn in) and shell fastenings of sea connections examined and found or placed in good condition:

Reps. due to W. & Ear; - The old 4 bladed Solid Cast Iron Propeller - the blades of which were badly  
wasted at tips - taken off & kept as spare. The Spare propeller also solid C.I.  
now fitted as Working Propeller.

The 2 Main Boiler Safety Valves; The Supt stated that all the S.V.s (Main & Spt.) had given trouble - leaking at pressures below the WP. (285 lbs.). These Valves & Chests complete were taken off & sent to Messrs Cockburn's Cardonald, for exam<sup>n</sup> & overhaul. See copy of Glasgow Certif. no C. 36679 dated 3/10/58. Valves refitted and adjusted under steam as stated above. As stated in Glasgow Certif, New double S.V.s are being made and will be fitted at the first convenient opportunity.

neral Observations, Opinion, and Recommendation:— The Machinery of this Vessel is (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, ~~✕~~ L.M.C. 9,11, or ~~✕~~ L.M.C. 140 lb., F.D., &c.)  
CS 3,34,  
in good safe working condition, eligible in my opinion to remain as now classed and to have record TS ex. 9.38.

y Fee (per Section 20)..... £ ✓ : : Fees applied for  
 \_\_\_\_\_ 19 \_\_\_\_\_  
 al Damage or Repair Fee (if any)..... £ ✓ : :  
 (per Section 20.)  
 lling expenses (if chargeable)..... £ ✓ : :  
 \_\_\_\_\_ 19 \_\_\_\_\_

Received by me, *A. Watt* © 2020  
 Engineer Surveyor to Lloyd's Register of Shipping

Committee's Minute \_\_\_\_\_ FBI 28 OCT 1938 \_\_\_\_\_  
Signed \_\_\_\_\_ As how \_\_\_\_\_