

Report of Survey for Repairs, &c., of Engines and Boilers.

10 FEB 1937

(Received at London Office)

Date of writing Report 5th Feb. 1937 When handed in at Local Office 9/2 1937

Port of ANTWERP

No. in Reg. Book. Survey held at ANTWERP
4688 on the Machinery of the Wood, Iron or SteelDate, First Survey and Last Survey 30-1-1937
S/S "HOPESTAR" (No. of Visits 1)Tonnage { Gross 5267
Net 5192

Vessel built at Newcastle

By whom Swan, Hunter & Wigham When 1936-8

Nominal Horse Power 400

Engines made at Wallend

By whom Bristol Marine Steam When 1936

No. of Main Boilers 2

Boilers, when made (Main) 1936

(Donkey)

No. of Donkey Boilers 1

Owners Wallend Shipping Co. Ltd.

Owners' Address

(if not already recorded in Appendix to Register Book.)

Steam Pressure in Main Boilers 285

Managers Arthur Stott & Co. Ltd.

Port Newcastle

Voyage

in Donkey Boilers 140

If Surveyed Afloat or in Dry Dock

Berth No 245

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
X for Special Survey
Date of last Survey and of
Periodical Surveys.Year
assigned
expired.Machinery and Boiler
Surveys
(including date of N.B. if any).+ 100 A 1
with freeboard
11 1/2 56+ LMC 2, 56
Ck

Last Report No. 94435 Port Newcastle

Particulars of Examination and Repairs (if any) Boiler repair

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

If this was not done, state for what reasons?

Boilers not due for survey

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler.

Present condition of funnel(s).

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam? Safety valves of superheaters 285 lb/1.

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Has screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons.

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft.

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft.

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Complete.

Now Done.

Starb. and Port Main boilers: superheater safety valves overhauled. Starb. boiler superheater safety valve spring renewed. The superheater safety valves of both Main boilers afterwards adjusted under steam to 285 lb/1 pressure.

General Observations, Opinion, and Recommendation:—The machinery of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.M.S. 9, 11, L.M.C. 9, 11, or CS 3, 34.)

so far as seen, is in good condition and is eligible, in my opinion, to remain as classed without fresh record of survey.

Survey Fee (per Section 29) 25.0

Fees applied for

Special Damage or Repair Fee (if any) £

4-2-1937

Travelling expenses (if chargeable) £

Received by me, 19

Committee's Minute

FRI 19 FEB 1937

Assigned As now

Engine Surveyor to Lloyd's Register of Shipping.

© 2020

Lloyd's Register
Foundation

W1013-0318

Has a Survey also been held on Ship?

If so, is the Report sent now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to

Superheated safety valves repaired.

It is submitted that
this vessel is eligible to
remain as CLASSED.

L4
15/2/36.



© 2020
Lloyd's Register
Foundation