



T.S.M. "LOCHMONAR"

No 2 Damage: - No 4 generator engine, No 2 crankshaft journal fractured.

Crankshaft to renew and engine to stop for examination

No 3 Damage: - No 1 crankpin bolt broken, No 1 crankpin scored, connecting rod bent, piston & liner broken, entablature bed plate fractured. Bed plate, entablature

liner, piston, connecting rod, crankpin brasses, etc. Engine to completely dismantle for survey, crankshaft to try in lathe for truth and make


No 2 crankpin

In view of the extensive damage to the hull of this vessel, it has not yet been decided whether vessel will be repaired or broken up.

Vessel has now been stripped of fittings and is lying at a buoy in the Solent, awaiting the Owner's decision.

No repairs have yet been carried out.

J. J. ...



© 2020

Lloyd's Register Foundation