

Report of Survey for Repairs, &c., of Engines and Boilers.

SAT. MAY. 11. 1912

No. 7374

Port of MIDDLESBROUGH Date, First Survey 1st April Last Survey 2nd April 1911

Survey held at Middlesbrough on the Machinery of the Wood, Iron or Steel Richardson, Westgarth & Co. Ld. Hpl. No. 1301 Master

Vessel built at By whom Engines made at By whom Boilers, when made (Main) (Donkey) Owners Port Voyage If Surveyed Afloat or in Dry Dock Richardson, Westgarth & Co. Boiler Shop

Particulars of Examination and Repairs (if any) Three Main Boilers

Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on damage (the cause of which must be stated) should be separated from repairs due to other causes; and being detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

Where cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were not?

Was a damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey " " " " " "

Parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boiler?

Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Screw shaft now been drawn and examined? Is it fitted with continuous liner? or two liners? or is it without liners?

Shaft now been changed? If so, state reasons

Shaft now fitted new? Has it a continuous liner? or two liners? or is it without liners?

Distance between lignum vitae of stern bush and top of after bearing of screw shaft?

Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Richardsons, Westgarth & Co. Ld. Middlesbrough No. 5239 J. Priestman No. S.S. No. 238

Richardsons, Westgarth & Co. Ld. Hartlepool No. 1301

Shell plates for three main boilers planed & rolled, butt straps

& front & back end flanged plates fitted to shells, shells completely

drilled & butt straps & back end plates satisfactorily riveted into

shells. Longitudinal seams pitch of rivets 10 3/8 x 1 19/32 dia rivet holes.

These boiler shells & ends have now been sent to Hartlepool

where the construction of the boilers is to be completed.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9, 10, B.&M.S. 9, 10, or L.M.C. 9, 10, 140 lb., F.D., &c.)

This is sent for the information of the Committee.

Committee's Minute

Assigned

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRI. FEB. 14. 1913

sa Minute on Hpl R/R 14538

© 2020 Lloyd's Register Foundation