

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

20 APR 1945

Date of writing Report 5-4-1945 When handed in at Local Office 1945 Port of Ipswich

No. in Survey held at Kings Lynn + Lowestoft Date First Survey 17 Jan Last Survey 3-2-4-5 1945
No. of Visits 5

417 on the Machinery of the Wood, Iron or Steel m.v. "MUDD"

Gross 218 Vessel built at Fenchel By whom m.v. Schips Fenchel When 1930

Net 130 Engines made at By whom Appingedammer Brons When

Nominal Horse Power Boilers, when made (Main) (Donkey)

No. of Main Boilers Owners D. Dosh Owners' Address

No. of Donkey Boilers Managers (if not already recorded in Appendix to Register Book.)

Steam Pressure in Main Boilers If Surveyed Afloat or in Dry Dock Both Port Swingen Voyage

in Donkey Boilers Particulars of Classification which must be inserted precisely as in Register Book & Supplements.

ast Report No. Port

Particulars of Examination and Repairs (if any) Gen. Ex. Drg. + S.R.L.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

as a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

not, state for what reasons? What parts of the Boilers could not be thus thoroughly examined?

That special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler. Present condition of funnel(s) Satisfactory

Did the Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Has the screw shaft now been drawn and examined? Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end? yes

Has shaft now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner? yes

Is approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft State the wear down in the

In bush blue fit Is electric light and/or power fitted? yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? yes

The insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? yes

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

has done:- Vessel placed in dry dock, propeller, after end of stern tube and outside fastenings of sea connections examined.

Examined all main engine cylinders, covers, pistons, valves and

valve gears, connecting rods, gudgeon pins, clutches, bottom end bearings

main bearings, crankshaft journals and crankpins, scavange blowers,

attached pumps and holding down bolts & all found or placed in

efficient condition.

Repairs due to W & T:- Main engine removed ashore and opened out

in its entirety, crankshaft placed in lathe and tested for truth, all

main bearing and nos 1 & 2 bottom end bearing metal found loose

or cracked and now renewed, piston rings renewed where necessary

and other minor repairs effected. P.T.O.

General Observations, Opinion, and Recommendation:- The machinery of this vessel, so

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 & LMC 9,11 or & LMC 140 lb., PD, &c.)

as has been seen, is in a safe working condition and eligible in our

opinion to have fresh record of Examined L.R. 3, 45 (12 months) when

the clutch gearing has been renewed as previously recommended.

Survey Fee (per Section 29) £ 10 : 10 : - Fees applied for

Special Damage or Repair Fee (if any) £ : : 20 APR 1945

(per Section 29.)

Travelling expenses (if chargeable) £ : : Received by me, 19

Committee's Minute TUES. 15 MAY 1945

Assigned As now subject

FZ. Turpie + J. J. Russell.

Engineer Surveyor to Lloyd's Register of Shipping.

© 2020

Lloyd's Register

Foundation

W1035-0115

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to

S.R. LIST

clutch gear

The new gear did not arrive for fitting at this port (see letter attached).

Examined clutch gearing completely opened out. broken & flat wheels dressed up and clutch plates renewed on account of same being found slack in meshing keys.

The gearing is considered satisfactory meantime and requires renewal as previously recommended.

Electrical Installation

Generally examined and megger-tested with satisfactory results.

On completion of foregoing repairs the main and auxiliary machinery was examined under working conditions & found satisfactory.

F. J. Turpin & J. J. Smith.



© 2020

Lloyd's Register
Foundation