

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office

24 JUL 1948

Date of writing Report

19

When handed in at Local Office

12 JUL 1948

Port of

NEWCASTLE-ON-TYNE

Survey held at

South Shields

Date. First Survey 28.6.48 Last Survey 5.7.1948

on the Machinery of the ~~Wood, Iron or Steel~~ s.s. "WARREN GROVE"

(No. of Visits 3)

Gross 351.
Net 139.

Vessel built at South Shields

By whom Heppler (1919) Ltd.

Year. Month.

When 1921 3

Horse Power 65 RHP

Engines made at South Shields

By whom Heppler (1919) Ltd.

When 1921.

Main Boilers 186.

Boilers, when made (Main) 1921

(Donkey) ✓

Donkey Boilers

Owners Challis, Sten & Co.

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port GLASGOW.

Voyage

Main Boilers 130 lbs/0

If Surveyed Afloat or in Dry Dock

Afloat

Donkey Boilers

(State name of Dock.)

(Dorman's Telly, Tyn Dock)

Report No. Port

Particulars of Examination and Repairs (if any) BS. SKL.

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he has rendered his services for this purpose, and why they were declined.

Has a damage report made by anyone else? If so, by whom?

Has the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *Yes.*

" Donkey " " "

Was not done, state for what reasons

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler 28.6.48.

Present condition of funnel *Efficient.*

Has the Surveyor examine the Safety Valves of the Main Boiler? *Yes.*

To what pressure were they afterwards adjusted under steam? 130 lbs/0.

Has the Surveyor examine the Safety Valves of Donkey Boiler? *Yes.*

To what pressure were they afterwards adjusted under steam?

Has the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? *Yes.*

and of the Donkey Boilers? ✓

Has the Surveyor examine the drain plugs of the Main Boilers? *Yes.*

and of the Donkey Boilers? ✓

Has the Surveyor examine all the mountings of the Main Boilers? *Yes.*

and of the Donkey Boilers? ✓

Has the screw shaft now been drawn and examined? *No.*

Is it fitted with continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has the shaft now been changed? ✓ If so, state reasons

Has the shaft now fitted been previously used? ✓

Has it a continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has the examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft.

When the parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted *Yes.*

Has the Surveyor examine the generators, motors, switchgear, cables and fuses? *No.*

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

Is the survey not complete, state what arrangements have been made for its completion and what remains to be done *Complete.*

Remarks: - Boiler examined in its entirety with its mountings, doors & fastenings; but not specially examined; boiler examined under steam and safety-valves adjusted 130 lbs/0.

U & T Repairs: - Port co. the wrapper plate bridge stays renewed (corroded). Appon. plain tubes renewed & a few tubes re-expanded (leaking). Bottom manholes & doors all up by electric welding & refitted. Butt strap seams & riveting overhauled & caulked where slight leakage had taken place. On completion of repairs, boiler examined under steam at full working pressure and found tight and satisfactory.

Repairs: - Ballast pump overhauled. Appon. 15 tubes in main condenser (leaked) renewed.

General Observations, Opinion, and Recommendation: - The machinery of this vessel is in

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 2, 11, B.E.S. 2, 11, & L.M.C. 2, 11, or L.M.C. 140 lb., F.D., &c.)

Order and eligible in my opinion to remain as classed in the Register Book with fresh record of BS 7.48, subject to boiler butt straps being specially examined by 7.49 (12 mrs. limit).

Fee (per Section 29) £4: -

£4: -

Fees applied for

Damage or Repair Fee (if any) (per Section 29.)

£: -

23 JUL 1948

Expenses (if chargeable)

£: -

Received by me,

LICENCE SUPERVISION

Committee's Minute

11 AUG 1948

Signed

BS 7.48 subject

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W1070-0260