

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 29th Dec 1920 When handed in at Local Office 9 FEB 1921 (Received at London Office 9 FEB 1921)
 No. in Reg. Book Survey held at Brightlingsea Port of Spain London
 on the Machinery of the Wood, Iron or Steel Co. K. "Samuel Drake" Date, First Survey Oct 29th 1920 Last Survey 10th Dec 1920
 (No. of Visits 5) Master YEAR. MONTH.

Tonnage { Gross _____
 Net _____
 Registered {
 Horse Power {
 No. of Main Boilers _____
 No. of Donkey Boilers _____
 Steam Pressure in Main Boilers _____
 in Donkey Boilers _____
 Vessel built at Paisley By whom Row. McLachlan When 1915-12
 Engines made at Liverpool By whom Lawcett Preston & Co When 1918
 Boilers, when made (Main) 1918 (Donkey) _____
 Owners The Admiralty Port London Voyage Fishing
 If Surveyed Afloat or in Dry Dock Afloat & Aldous
 (State name of Dock.) Refway. Brightlingsea

Last Report No. _____ Port _____
 Particulars of Examination and Repairs (if any) Admiralty
Recondition

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.	Year Assigned now required.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>B.C. class</u>		<u>B.C. class</u>

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ☒ Was a damage report made by anyone else? If so, by whom? ☒

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " " " ☒

If this was not done, state for what reasons? ☒

And what parts of the Boilers could not be thus thoroughly examined? ☒

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ☒

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes

To what pressure were they afterwards adjusted under steam? 180 lbs.

Did the Surveyor examine the Safety Valves of Donkey Boiler? ☒

To what pressure were they afterwards adjusted under steam? ☒

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes

, and of the Donkey Boiler? ☒

Did the Surveyor examine the drain plugs of the Main Boilers? ☒

, and of the Donkey Boiler? ☒

Did the Surveyor examine all the mountings of the Main Boilers? Yes

, and of the Donkey Boiler? ☒

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? Yes or two liners? ☒ or is it without liners? ☒

Has shaft now been changed? No If so, state reasons ☒

Is the shaft now fitted new? ☒ Has it a continuous liner? ☒ or two liners? ☒ or is it without liners? ☒

State the distance between ligament of stern bush and top of after bearing of screw shaft? 1/8" bare

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

Now Done: The cylinders, pistons, valves, condensers, pumps (main & auxiliary) with connections, crank & thrust shafts with bearings, opened up & examined. The propeller tail shaft, stern tube & bush examined. Sea cocks & valves opened up & examined with their fastenings. Boiler examined internally & externally & mountings opened up and examined. Boiler examined under steam & Safety valves adjusted. The machinery together with Pumping arrangement throughout vessel tried under working conditions and found satisfactory.

Repairs Effected 2 feed pump plungers skimmed & new gland & neck bushes fitted. New spindle for donkey discharge valve on ship's side. Ridge filed off M.P. slide valve face. 1 Screw stay Caused & 1 new nut in star furnace back end. Slight leaks Caused in back ends & on circum steam boiler. Propeller refitted on cone & shaft. Boiler mountings, Sea cocks & valves overhauled as required.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9, 11, E.&M.S. 9, 11, or L.B.C. 9, 11, 140 lb., F.D., &c.)

The machinery of this vessel is now in good working condition & eligible in my opinion to have the Record of L.M.C. 12.20 with "Screw Shaft Examination" 12.20 in the Society's Register Book

Survey Fee (per Section 25) _____
 Special Damage or Repair Fee (if any) (per Section 25.) _____
 Travelling Expenses (if chargeable) _____
 Fees applied for _____
 Received by me; _____

Robert Rae
 Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI JUL 1 1921

Assigned L.R. 12.20



© 2020

Lloyd's Register Foundation

N1075-0052