

S.S. GRAPHIC

below deck in way of engine & boiler spaces renewed. All engine & boiler & tunnel platforms renewed, bilges cleaned & recoated & platforms replaced or extensively renewed. All woodwork in chain locker & stores renewed & extensively renewed. All bilges cleaned & recoated. All double bottom tanks & peak tanks cleaned & examined internally, tested & found or made tight. All bilge, tank, service, air sounding pipes, steam & exhaust piping, scuppers, drains, soil pipes, heater pipes &c overhauled, removed where necessary to effect repairs, or where damaged, new renewed or repaired. Side scuttles & windows overhauled & damages renewed. All steelwork sealed & recoated & vessel generally reconditioned. Upholstery & furnishings reconditioned or renewed as found necessary.

Damage stated sustained in collision with the Fleetwood steamer H^o 1 fore-castle side plate foot & starb^o removed. Beading & jackstay on starb^o side removed & replaced. also all internal fittings

Damage stated sustained by contact with quay. On starb^o side forward of midships, indented shell plating failed in place and one length of wood fender renewed.

2nd S.S. H^o 3. At the owners' desire, in view of the extensive repairs occasioned by the above mentioned collision & the consequent removal of all linings, the vessel was submitted to the 2nd special survey H^o 3.

Vessel placed in drydock, bottom & under deck scanned & examined & recoated. Holds, peaks, bunkers, engine & boiler spaces (coal bunkers & boiler removed) examined, sealed & recoated. All lining & ceilings & floorings removed. Outside plating drilled, & found satisfactory; results given below. All double bottom tanks & peak tanks cleaned, examined internally, recoated, tested & found satisfactory. Cables ranged. Masts (wedges removed), rigging, general equipment, ventilators, coamings & covers, decks, pumps, (land & steam) hatches throughout, watertight doors, air sounding pipes, windlasses, steering gear & its connections examined & found or made satisfactory. Freeboard verified

Thickness in ^{1/32} of an inch	In way of original coal bunkers.			4 feet aft of engine room.			Centre of H ^o 3 hold & in way of beams of bridge deck.		
	Port	Starb ^o	Keel	Port	Starb ^o	Keel	Port	Starb ^o	Keel
Main & sheer trake	16	15	16	16	16	16	18	18	18
1 st strake below	10 1/2	12	12	13	12	12	10	10+	12
2 nd " "	11	12	11	11+	13	11	11+	12	11
3 rd " "	13+	13	12	12	13+	12	12	13+	12
4 th " "	13+	13	12	12	11+ and 12	12	13	12	12

S. GRAPHIC.

Vessel fitted for burning oil fuel. F.P. above 150° F. Two double ended & one single ended boilers removed & one double ended & two single ended boilers fitted. Coal bunkers removed & 2 oil bunkers fitted each side of double ended boiler, in accordance with approved plan & Secy's letter 14.17.8.93.

Strong beams & coamings replaced. Puller fitted in boiler space as found necessary. Oil bunkers tested with a head of water 20 feet above crown of bunker & made tight. Plan of oil bunkers retained for dealing with similar job on sister vessel "S. Heron" now under survey here & fitted for burning oil fuel.

Wear & tear repairs. 11 frames in bridge space fitted with reverse bars on starboard side & 7 on port side. 13 frames starboard & 7 port in bridge space strengthened at main deck by continuous gussets.

8 frames in wt. aft (sp 225) repaired & wt. bulkhead part doubled. Main deck in way of forecast, 1 plate part renewed & at lower deck, the tie plating in way of main part renewed.

In way of forecast the end coaming of wt. & coamings in alleyways part renewed & deck doubled. In boiler space.

8 side keelson intercostals renewed. 5 floor top bars p 15 part renewed. 8 reverse bars part renewed at bridge (sp 785)

Quantity of riveting of side stringer shell legs in fore peak tank renewed with 3/4" rivets. Quantity of deck planking renewed & hatch covers extensively renewed. Several ventilator coamings renewed.

W. M. Aspinall