

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 29 December 1921 When handed in at Local Office 30.12.1921 Port of NEWCASTLE-ON-TYNE

No. in Reg. Book. 26591 Survey held at North Shields Date, First Survey 29 Nov Last Survey 23 December 1921 (No. of Visits 11)

on the Machinery of the Wood, Iron or Steel S.K. "Othello" Master Bochrane & Sons

Tonnage { Gross 201 Net 94 Vessel built at Selby By whom Bochrane & Sons When 1907-10

Registered Horse Power 67 Engines made at Hull By whom B.D. Holmes & Co When 1907

No. of Main Boilers 1 Boilers, when made (Main) 1921 (Donkey)

No. of Donkey Boilers None Owners A. Bannister Port Grimsby Voyage

Steam Pressure in Main Boilers 180 lb If Surveyed Afloat or in Dry Dock Shields Eng. Co. Ltd. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boilers ✓ (State name of Dock.)

Last Report No. Port has main boiler fitted

Particulars of Examination and Repairs (if any) fitted

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do " Donkey " " Main boiler " renewed.

If this was not done, state for what reasons? Main boiler renewed.

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? 185 lb

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? he , and of the Donkey Boiler? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? no , and of the Donkey Boiler? ✓

Did the Surveyor examine all the mountings of the Main Boilers? yes. , and of the Donkey Boiler? ✓

Has screw shaft now been drawn and examined? yes. Is it fitted with continuous liner? yes. Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? no.

Has shaft now been changed? no. If so, state reasons ✓

Is the shaft now fitted new? no. Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? a good fit.

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? ✓

Now done:- The main boiler removed from vessel, and replaced by multitubular boiler for particulars please see Middlebro' report no 11135.

Main steam pipe renewed. Tested to 360 lb. water pressure before fitting.

Boiler mountings examined, and safety valves adjusted under steam to the above pressure.

The propeller, tailshaft, sternlark and sea connections

General Observations, Opinion, and Recommendation:- The machinery of this

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9, 11, B.&M.S. 9, 11, or L.M.C. 9, 11, 140 lb., F.D., &c.)

vessel as far as seen is in good order and safe working condition and eligible in my opinion to remain as classed and to have the notation + NB 12-21 and TS 12-21

GS 26. HS 1110. 1295. 2/4. TUES. 2 NOV 1926

TUES. 30 AUG 1927

TUES. 4 MAY 1926

TUES. 1 MAR 1927

Engineer Surveyor to Lloyd's Register of Shipping.

FRI. 25 SEP 1925

TUE JAN 20 1925

TUE FEB 20 1925

TUES. 7 OCT 1924

FRI. 9 JUL 1925

FRI. 24 JUL 1925

FRI. 12 APR 1929

Survey Fee (per Section 28) 2 Fees applied for 30.12.1921

Fitting on board 3 3 0 Received by me, 19 22

Special Damage or Repair Fee (if any) (per Section 28.) 2

Travelling Expenses (if chargeable) 2

Committee's Minute TUE JAN 10 1922

Assigned + NB 12-21

Lloyd's Register

Foundation

W1105-0138

A new main boiler has been fitted, screw shaft examined & a new propeller fitted.

It is submitted that this vessel is eligible for

THE RECORD. + NB 12.21.

S12.21.

20/5. 65 36. HS 1295.

Expenditure £2.19.

W.D.

7/1/22.

"Othello". (continued)

Together with fastenings examined.

Propeller (cast iron, solid.) examined.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE



© 2020

Lloyd's Register Foundation