

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 27 SEP 1941)

Date of writing Report 17th. Sept 19 41 When handed in at Local Office 19 Port of LISBON

No. in Survey held at Lisbon Date First Survey 13th. Sept. Last Survey 17th. Sept. 19 41
Reg. Book 55038 on the Machinery of the Wood, Iron or Steel CABO S. VICENTE (No. of Visits 2)

Gross Tonnage 269 Vessel built at Selby By whom Cochrane & Sons. When 1910-9
 Net Tonnage 103 Engines Made at Hull By whom Amos & Smith Ltd. 1910
 Nominal Horse Power 80 Boilers, when made (Main) 1910 (Donkey) -
 No. of Main Boilers 1 SB Owners Soc. Comercial Maritima Ltda. Owners' Address -
 No. of Donkey Boilers - Managers - (If not already recorded in Appendix to Register Book).
 Steam Pressure in Main Boilers 200 lbs. If Surveyed Afloat or in Dry Dock No. 3 D.D. Port Lisbon Voyage -
 in Donkey Boilers - (State name of Dock).

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey Date of last Survey and of Periodical Surveys.	Years since last survey	Machinery and Boiler Surveys (Including date of N. B., if any).
+100A1		+L.M.C.
Stm. Trawler		10,40
10,40		
ss. Snd. No. 3-9, 36		CL. 10,40
ss. Lis. No. 1-40		

Particulars of Examination and Repairs (if any) B.S. & Dkg.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined -

Was a damage report made by anyone else? If so, by whom? -

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Donkey -

If this was not done, state for what reasons -

And what parts of the Boilers could not be thus thoroughly examined? -

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -
State latest date of internal examination of each boiler 13-9-41

Present condition of funnel(s) Good

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 200 lbs.

Did the Surveyor examine the Safety Valves of Donkey Boiler? - To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers? -

Did the Surveyor examine the drain plugs of the Main Boilers? None, and of the Donkey Boilers? -

Did the Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boilers? -

Has the screw shaft now been drawn and examined? No Is it fitted with continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

Has shaft now been changed? - if so, state reasons -

Has the shaft now fitted been previously used? - Has it a continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

State date of examination of Screw Shaft - State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 2 m/m

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted -

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? -

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? -

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Now Done:- Vessel placed in dry dock, propeller and all outside fastenings examined and found good. The main boiler opened out and examined together with its safety valves and other mountings and found in good order. The safety valves adjusted as above and the boiler examined under steam and found satisfactory.

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, B.M.S. 9.11, L.M.C. 9.11, or L.M.C. CS 3,34, 140 lb., F.D., &c.)

The machinery of this vessel in my opinion is eligible to remain as classed with fresh record of B.S. 9,40.


941

Survey Fee (per section 29) BS. Esc: -330\$00 Fees applied for 17/9/ 1941
 Special Damage or Repair Fee (if any) £ -:-
 Travelling expenses (if chargeable) Esc: - 20\$00 Received by me, 19

Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI. 10 OCT 1941

Assigned BS 9.41



© 2021

Lloyd's Register Foundation

W1125-0086

Insert Character of Ship and Machinery precisely as in the Register Book

AS held

It is submitted that
this vessel is eligible for
THE RECORD. 124941

ASA
8/10/41

It is submitted that this vessel is eligible for THE RECORD.

SPECIFICATIONS	
Year	
Make	
Model	
Capacity	
Weight	
Dimensions	
Other	



© 2021

Lloyd's Register
Foundation