

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

16 JUN 1941

(Received at London Office)

17 JUN 1941

Port of

**HULL**

Date of writing Report	When handed in at Local Office	Date First Survey	Last Survey
No. in Reg. Book.	Survey held at <b>Hull</b>	"CARSBRECK"	(No. of Visits) 27
71814	on the Machinery of the <del>Vessel</del> , Iron or Steel	27 JUL 1941	6 JUL 1941
Tonnage	Gross 3670 Net 2254	Vessel built at <b>Irvine</b> Engines made at <b>Glasgow</b>	By whom <b>Ayrshire Docks &amp; Co Ltd.</b> When 1936-9
Nominal Horse Power	346	Boilers, when made (Main) 1936 Owners <b>Gardiner S. S. Co. Ltd.</b>	By whom <b>D. Rowan &amp; Co Ltd.</b> When 1936
No. of Main Boilers	255	Managers <b>Honeyman &amp; Co.</b>	Owners' Address (if not already recorded in Appendix to Register Book.) Port <b>Glasgow</b> Voyage
No. of Donkey Boilers	1	Surveyed Afloat or in Dry Dock <b>Alexandra Dock</b> and <b>Dock</b>	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
Steam Pressure— in Main Boilers	200 ft		CHARACTER X for Special Survey Date of last Survey and of Periodical Surveys.
in Donkey Boilers	100 ft		Years since last Survey (including date of N.B. if any).

Last Report No. Port

## Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey " "

If this was not done, state for what reasons

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler.

Main 19.3.41 Donkey 17.4.41 Present condition of funnel(s)

Good

Did the Surveyor examine the Safety Valves of the Main Boiler?

Yes

To what pressure were they afterwards adjusted under steam?

200 ft

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Yes

To what pressure were they afterwards adjusted under steam?

100 ft

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Yes

, and of the Donkey Boilers?

Yes

Did the Surveyor examine the drain plugs of the Main Boilers?

None

, and of the Donkey Boilers?

None

Did the Surveyor examine all the mountings of the Main Boilers?

Yes

, and of the Donkey Boilers?

Yes

Has the screw shaft now been drawn and examined?

Yes

Is it fitted with continuous liner?

Yes

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

✓

Has shaft now been changed? If so, state reasons.

No

Has it a continuous liner?

Yes

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

✓

Has the shaft now fitted been previously used?

Yes

State date of examination of Screw Shaft 17.3.41 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft.

1/8

State date of examination of Screw Shaft 17.3.41 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft.

Engine parts, when referred to by numbers, should be counted from forward.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Yes

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Yes

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

complete. Wait you

On account of damage, static to have been caused by enemy action in the North Atlantic on 17th October 1940 whilst on a voyage from Nova Scotia to Grindly, (See G.R. nos 63283 & 63187), vessel placed in drydock. Examined propeller, screwshaft (a), sternbush, sea connections and fastenings. Examined main engine cylinders, piston, valves, crankshaft, thrust & intermediate shafts, condenser (busted), main and auxiliary pumps, pumping arrangements, dynamos, engine, switchboard & circuits, steam pipes and feed pipes. Particular care taken to look for fastenings in all castings. Examined bilges internally & externally with all mountings, doors & fastenings. Examined bilges under floors and adjusted safety valves on above. Machinery tried under working conditions and found satisfactory.

P.T.O.

**General Observations, Opinion, and Recommendation:** Eligible to remain as closed (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9/II, B.&H.S. 9/II, \*L.M.C. 9/II, or L.M.C. 140 ft., F.D., &c.)

with fresh record of \*L.M.C. 6,41 and T.S.(a) 841

Survey Fee (per Section 29)	LMC £ 12.0 : 0	Fees applied for 16 JUN 1941
Special Damage or Repair Fee (if any) (per Section 29)	£ 12.12 : 0	
Travelling expenses (if chargeable)	£ :	Received by me, FRI. 4 JUL 1941

Committee's Minute

Assigned

16 JUN 1941 Without  
Cont. CERTIFICATE WRITTEN.

W. J. Shields  
Engineer Surveyor to Lloyd's Register of Shipping.

© 2020



## S.S. "CARSBRECK"

Damage Repairs:-

Steam pipes above 3.75 bore to essential services and feed pipes removed ashore and "replaced".  
 A number of plain tubes in boiler replaced.  
 Superheat elements removed ashore and repaired or renewed as required.  
 Steering engine pinion and spur wheel renewed.  
 Guide plate (fractured) and column removed ashore and guide face machined.  
 General service pump water end liner renewed.

\* LMC.

Owners' representative requested that this examination be accepted for fresh record of \*LMC and this request in my opinion merits ~~the~~ favourable consideration of the Committee.

W.H.S. Shields.

"I consider that it is most generally known and used at sea, several thousand (T.B.C. & C.R.C. on 28th Oct) pieces of steel used with copper or tin wire (O.P.I. 1200) for anti-corrosive use, particularly (a) galvanised, (b) painted, (c) varnished. Steel is hard metal, after disintegration of paint, galvanised, oxide, oxidise, oxidized iron may become oxidized, rusted, eroded, damaged, fractured, abraded, pitted and worn, (which) causes oxidation of metal and reduced strength. Rust may form rapid mould, disease, destruction, degradation, loss, deterioration of metal, pitting, pitting and damage. Oxidized sea is pitting iron with pitting, surface and paper, bitumen and metal, when oxidized becomes protection and sea conditions.

D.T.9

Wooden or ironed &amp; stings

mark (a) 87 and 141.3 CM 1\* to small part of

0.051

0.51 51

PMC

© 2020

Lloyd's Register  
Foundation