

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 29 JUL 1942)

Date of writing Report _____ When handed in at Local Office 20/7/42 Port of NEWCASTLE-on-TYNE

No. in Reg. Book 23286 Survey held at South Shields Date, First Survey 19 June Last Survey 17 July 1942
 on the Machinery of the Wood, Iron or Steel s.s. EMPIRE SOLDIER (No. of Visits 3)
 (ELEC 4)

Tonnage } Gross 4539 Vessel built at Port Glasgow By whom Littgows, Ltd. Year. Month. 1928. 8.
 Net 2743 Engines made at Greenock By whom Rankin & Blackmore When 1928

Nominal Horse Power } 474 Boilers, when made (Main) 1928 (Donkey)
 No. of Main Boilers 3 Owners Ministry of War Transport Owners' Address _____
 No. of Donkey Boilers Managers Wm. Cory & Son, Ltd. Port London Voyage
 Steam Pressure in Main Boilers 200 lbs If Surveyed Afloat or in Dry Dock Dry & afloat
 in Donkey Boilers (State name of Dock.) Brougham & Bowdler, Ltd.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. _____ Port _____
 Particulars of Examination and Repairs (if any) E.E. & Docking

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time?

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler _____ Present condition of funnel Efficient

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons _____ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft _____ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 1/8"

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted? Light

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? Electrical Report attached.

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Now done:- Vessel placed in drydock, propeller and outside fastenings examined and found efficient.

E.E. The following items examined during course of overhaul.

Main Injection Valve. — Reconditioned.

Main Engines. — H.P. piston valves and cage. — Adjusted.

M.P. cylinder, piston, valves and valve chest.

Nº 6 main bearing. Top half reinstalled.

Owners Representative states that machinery has been giving satisfaction. Main & Auxiliary machinery now examined under working conditions and found efficient.

General Observations, Opinion, and Recommendation: — The Machinery of this vessel, so far

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 2, 11, B.S.M.S. 2, 11, & L.M.C. 2, 11, or X.L.M.C. 140 lb., F.D., &c.)

as now seen, is in efficient condition, and eligible, in my opinion, to remain as classed, with fresh notation, "Examined 7, 42" (for 12 months).


Form R-1 attached Rpt. 8

Survey Fee (per Section 29) £ 2.2.0 Fees applied for 28 JUL 1942

Special Damage or Repair Fee (if any) £ _____
 (per Section 29.) License Case

Travelling expenses (if chargeable) £ _____
 Received by me, E. Wilson
 Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI 7 AUG 1942
 Assigned As now



Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

20 JUL 1942

EMPIRE SOLDIER

Electrical equipment.

General examination and wear and tear repairs.

The wiring in the boiler room was partly removed and the pump lights repaired, the wiring in the engine room was partly removed and replaced and earth faults cleared.

Faults were removed in the wiring of the captain's quarters and plug sockets fitted there and in the store room.

Wiring was removed in the aft accommodation, the navigation light circuits repaired and minor low insulation faults removed in different parts of the installation.

On completion the installation was operated under working conditions with satisfactory results and the insulation resistance of all circuits measured and found good.

This equipment is now in my opinion in good order and safe working condition.

W. H. Cornell

Fee £2.2.0 - See Rpt 9.



No. 3 Ave & 40 part held 841
G.C. now held.

It is submitted that this
vessel W.L.L. 1315, double
for the record, + 100000 841 on
completion
and examined 7/42
now.

The Surveyor should
state which of the
~~items~~ now reported
may be credited
to the Special
Fund.

See also 12/18/42
12/18/42

W.A.

James Hill

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page.]

11/1/41
10021