

8 - OCT 1942

(Received at London Office)

No. 100767

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 24th Sept. 1942When handed in at Local Office 25th Sept. 1942

Port of

NEWCASTLE-ON-TYNE

o. in
Book.

Survey held at WALLSEND-ON-TYNE

Date, First Survey 23rd JulyLast Survey 16th September 1942

931

on the ~~Wooden~~ Steel

"EMPIRE TURNSTONE" Ex "WESTERN CITY"

TONNAGE:-

Built at PORTLAND OR.

By whom COLUMBIA RIVER S.B. CORP.

When 1918

MONTH

ROSS 6113

Owners MINISTRY OF WAR TRANSPORT.

Owners' Address

(if not already recorded in Appendix to Register Book).

UNDER DEK 5129

Managers KAYE SON & CO. LTD

Port belonging to LONDON

ET 3714

urveyed Afloat or in Dry Dock? BOTH

Name of Dock WALLSEND SLIPWAY

Destined Voyage

ULDBorDBa

feet; uE&B

feet; f

feet

al capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

ast Report, No. 110625

Port Lon.

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

DOCKING.

NOW DONE: Vessel placed in drydock, bottom and rudder cleaned, examined and recoated and placed in good condition. Rudder lifted.

Decks, Casings, Hatchways, Hatches and Supports and Battening Arrangements, Vents, coamings and closing appliances, Air Pipes, Companionways, Fore and Aft Peak Tanks internally, Engine Room D.B. Fresh Water Tank and Oil Fuel Settling Tank in way of No. 3 hold internally, Masts, Rigging, Windlass, Steering gear and general Equipment examined generally and found or placed in good condition.

P.T.O.

SUMMARY OF DAMAGE REPAIRS:—

	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

ing of Decks	good	Bulkheads	Part Exam good	Engine Room Skylights	good	Copper, or Y.M.	
ings		Ceiling		Coal Bunkers, Openings, Covers, &c.		(State if on Felt.)	
s & Fastenings	Part Exam	Cement or Asphalt	good	Oil Bunkers	good	When fitted, Month	Year
le Plating		Rudder	good	Scuppers		Boats	good
in way of sidelights		Steering gear and its connections	good	Cargo Hatchways	good	Masts, Yards, &c.	good
Part Exam good		Windlass	good	Hatches	good	Condition, how ascertained	From Deck
se Frames		Have pumps been examined and found efficient?	✓	Planking		(State if wedges removed.)	
udinals		Have Sluice Valves been examined and found efficient?	✓	Caulking		Equipment letter	Z
verses	Part Exam good	Have Watertight Doors been examined and found efficient?	✓	Treenails		Anchors, No. of	3 B. 15. 1K.
ns		Have Ventilators and their Coamings been examined and found efficient?	yes	Breasthooks & Stemson		Cables (State if now ranged)	yes
ers		Air and Sounding Pipes	good	Transoms Pointers & Crutches		length 270 FMS	mean diamr 2 1/4"
Bottom Plating	good	Doubling Plates under Sounding Pipes	✓	Timbers of Frame at openings		(on board)	270 FMS
the Tanks been examined internally?	as report			Stringers, Clamps & Shelves		Rule length	270 FMS
the Tanks been tested?	as report			Salting	(State if examined.)	Chain Locker	good
						Hawsers & Warps	sufficient
						Standing and Running Rigging	efficient
						Sails	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel as now seen is in good condition and eligible in my opinion to remain as now classed in the Register Book, with fresh record of Docking, subject to Indented Plating (S.S.) in way of F.P. and Fore & Aft Ch. and Framing in way being permanently repaired at first opportunity.

Fee (per Section 29)

IMATED FEE £3.3.0

Damage or Repair Fee (if any)

per Sec. 29

ling Expenses (if chargeable)

Surveyor's Fee (if any)

CENCE CASE

Committee's Minute

Character Assigned


Fees applied for,

-7 OCT 1942

Received by me,

19

H. Little & H. G. Turnbull
Surveyors to Lloyd's Register of Shipping.



Lloyd's Register
Foundation

W1128-0296

The Fore and After Peak Tanks were pressure tested and minor leakages made good.
Engine Seating was examined whilst machinery was removed for repair and found in good condition.

WEAR AND TEAR REPAIRS. All side scuttles throughout ship overhauled as necessary.

S. R. L. Indented Plating (3.3.) in way of F.P. and Lo'ck Deck and framing in way examined and remains efficient meantime.

Renewal Freeboard Survey carried out at this time. Report forwarded.
All repairs carried out under licence NO. 4850.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.