

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 8 - OCT 1942)

Date of writing Report 19 7. 10. 42. Port of NEWCASTLE-on-TYNE

No. in Reg. Book. Survey held at Date, First Survey 18. 7. 42. Last Survey 28. 9. 1942

84981 on the Machinery of the Wood, Iron or Steel SS. "EMPIRE, TURNSTONE" (Electrical No. of Visits 20)

Tonnage Gross 5828 Net 3871 1/4 Vessel built at Portland Or By whom Columbia River S.S. Corp

Nominal Horse Power 551 Engines made at Welloville N.Y. By whom Kerr Turb Co When 1918. 6

No. of Main Boilers 3 Boilers, when made (Main) 1918 (Donkey) Owners' Ministry of War Transport Owners' Address

No. of Donkey Boilers 1 Managers Kaye, Son & Co Ltd Port London, Voyage

Steam Pressure in Main Boilers 210 If Surveyed Afloat or in Dry Dock Wallend Slipway

in Donkey Boilers Last Report No. Port

Particulars of Examination and Repairs (if any) Repairs TBS.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? Yes

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler 21. 8. 42. Present condition of funnel good.

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 210

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? Yes, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? Yes, and of the Donkey Boilers?

Has screw shaft now been drawn and examined? No. Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons. Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft. State the distance between lignum vite or bearing metal of stern bush and top of after bearing of screw shaft 7/32

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and power fitted? Yes

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Vessel in drydock. Propeller sea connections & fastenings examined

Turbine casing & rotor removed, from vessel & forwarded to Messrs Fraser & Chalmers Erith for repairs (See London Report)

afterwards refitted on board.

Main gears opened up, teeth dressed where necessary.

Thrust shaft examined & block lifted at forward end to correct alignment of shafting. Tunnel shafts examined

Condensers, feed heaters & lubricating oil & coolers cleaned & tested

all auxiliary pumps and dynamo engines examined

Main Boilers examined internally & externally with all (See continuation)

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.S.M.S. 9,11, & L.M.C. 9,11, or L.M.C. 140 lb. F.D., &c.)


The machinery of this vessel is eligible in our opinion to remain as Classed & have the Record BS 9.42.

Survey Fee (per Section 20) BS £ 4 : 0 : 0 Fees applied for 7 OCT 1942

Special Damage or Repair Fee (if any) Repairs £ 99 : 0 : 0 Received by me,

License Fee £ 2 : 2 : 0 Travelling expenses (if chargeable)

Committee's Minute TUE. 27 OCT 1942 Assigned As now, without spl edn B.S. 9.42



Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to the Registrar

Lloyd's Register Foundation W1128-0297 13

SS. "EMPIRE. TURNSTONE" ex "Western City"

18948
 their mountings & the safety valves adjusted under steam
 oil fuel pressure lines & fire extinguishing arrangement
 examined & found satisfactory

Repairs:-

Main Air Pump. Fan & fan engine & Evaporator and two
 oil fuel heaters renewed. Lubricating oil Coolers
 retubed.

Water end liners renewed in both main feed pumps
 & lubricating oil cooling pump. & a number of
 minor repairs & adjustments effected.

Steering engine & telemotor opened up, examined
 & overhauled.

The locking pin controlling the hand gear dog clutch
 became disengaged when vessel left the quay
 causing clutch to foul & damaging controls

1 C.I. bracket renewed, 1 bevel wheel renewed

1 bracket & 3 bevel wheels repaired. & 1 shaft straightened

Gear afterwards examined under working conditions
 & found satisfactory

Main & auxiliary machinery proved satisfactory
 under working conditions at quay.

Extension spindles fitted to Main injection

Emergency stop valve & steam control to oil fuel
 pump.

Gutterway & oil bilge with the necessary suction
 to oil fuel transfer pumps fitted & found
 satisfactory.

Roll H.G.

Electric Light Report attached.

WESTERN CITY 2-12.5KWElectrical equipment.Repairs and additions

A generator was removed and repaired, the navigation lights were repaired, and lights were fitted in the new gunners quarters.

On completion the equipment was operated under working conditions with satisfactory results and the insulation resistance measured and found good:— This equipment is now in my opinion in good order and safe working condition.

M. S. Corwell

Fee £2.2.0 See Rpt. 9

No. 542 Held

Fuel tank casing & bolts reconditioned & refilled. Gearing examined & other parts of machinery examined & found in order.

It is submitted that this vessel is eligible for THE RECORD.

No. 942

Without Special Condition

Thus

22.10.42

Vertical handwritten text, possibly a signature or date.

Main body of vertical handwritten text, likely a detailed report or log.

Vertical text on the right edge, possibly a reference number.