

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report 26-10-1940 When handed in at Local Office 31-10-1940 Port of Manchester

No. in Reg. Book 75002 Survey held at Manchester Date, First Survey and Last Survey 24 October 1940
(No. of Visits 0700)

Tonnage Gross 4393 Net 2649 Vessel built at Sunderland By whom Wm Doxford Sons Ltd When 1928. 4
Engines made at Sunderland By whom Wm Doxford Sons Ltd When 1928
(Donkey) 1928.

Nominal Horse Power 417. Boilers, when made (Main) Owners Moor Line Ltd Owners' Address (if not already recorded in Appendix to Register Book.)
No. of Main Boilers ✓ Managers Runciman Shipping Co Ltd Port London Voyage

No. of Donkey Boilers 2. Managers Runciman Shipping Co Ltd Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
Steam Pressure in Main Boilers ✓ £ Surveyed £ in Dry Dock Nº 2. Dry Dock
(State name of Dock.)

Last Report No. Port Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓
" " Donkey " " no

If this was not done, state for what reasons? DBS not due

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ , and of the Donkey Boilers? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? no

Has screw shaft now been drawn and examined? no Is it fitted with continuous liner? ✓

Has shaft now been changed? ✓ If so, state reasons ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? 1/8

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓

State date of examination of Screw Shaft ✓ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft ✓

Engine parts, when referred to by numbers, should be counted from forward. ✓

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

now done: Vessel placed in dry dock Propeller, outside fastenings examined and found in good condition

General Observations, Opinion, and Recommendation: the machinery of this vessel is in good condition and efficient condition and digible, in my opinion, to remain as classed without fresh record of survey

Survey Fee (per Section 29) £ 19
Special Damage or Repair Fee (if any) (per Section 29.) £ 19
Travelling expenses (if chargeable) £ 19

Fees applied for 19
Received by me, 19
G. B. Davis
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute Deferred
Assigned

W1129-0228



If so, is the Report sent now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book

Is a certificate required? If so, to be sent to

It is submitted that
this vessel is eligible to
remain as CLASSED,

SS No. 3 due 4.40. Seal
of grace approved.

F.Y.
13/11/40.



© 2019

Lloyd's Register
Foundation