

Received by Chief Engineer Surveyor \_\_\_\_\_

Received from Chief Engineer Surveyor \_\_\_\_\_

VESSEL'S NAME

*Fernando Poo*

Rpt.

*Bilbao*  
*Bcl.*

No.

*8673*  
*4208*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Type of Engine

*Oil Engines**12 Cy. 24  $\frac{7}{16}$ " - 45  $\frac{1}{4}$ " 2.S.C.S.A.*

If Boilers fitted with forced draught ✓

Tail Shaft. If fitted with a continuous liner *Yes*If fitted with an outside gland of }  
approved type *No*

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ L.M.C. 9.35*

*HR*  
*8.10.35**DA*

It is concluded that the Emergency dynamo was built under Survey in accordance with Sec. 2 Clause 6 of the Rules for Heavy Oil engines but this should be confirmed.

If the engine was built in his district the Surveyor should forward the usual report H.C. It should be also requested to state what the boiler can be used for.

See endorsement re elec motor attached to 'Domina' *8668.*

*for 19/10/35*

© 2021

Lloyd's Register  
Foundation

W1132-0130