

SUP

REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

No.

Report	When handed in at Local Office	Port of
Survey held at	Date. First Survey	Last Survey
Book. on the Machinery of the Wood, Iron or Steel	St. HELENA.	
Tonnage Gross 4313	Year.	
Net 2602		
Nominal Horse Power 304		
No. of Main Boilers 2	Vessel built at Sunderland.	By whom J. Thompson & Sons, Ltd. When 1926
No. of Donkey Boilers ✓	Engines made at Newcastle.	By whom White Star Line, Ltd. When 1926
Steam Pressure in Main Boilers 230 lb.	Boilers, when made (Main) 1926	(Donkey) ✓
in Donkey Boilers ✓	Owners V. Bunting Shipping Co. Ltd.	Owners' Address (if not already recorded in Appendix to Register Book.)
	Managers R.O.S. Shipping Co. Ltd.	Port Liverpool Voyage ✓
	If Surveyed Afloat or in Dry Dock Great George Dock.	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
	(State name of Dock.)	

Last Report No. 50839 Port Hull

Particulars of Examination and Repairs (if any) A.S.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined. ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes.

Donkey

If this was not done, state for what reasons. ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? {

State latest date of internal examination of each boiler. 28.12.40. 1.7.1.41. Present condition of funnel(s) good.

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes. To what pressure were they afterwards adjusted under steam? 220 lbs/psi

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes. , and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓ , and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? Yes. , and of the Donkey Boilers? ✓

Has the screw shaft now been drawn and examined? ✓ Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? {

Has shaft now been changed? ✓ If so, state reasons. ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? {

State date of examination of Screw Shaft. ✓

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. ✓

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? ✓

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

Time Done. Both main engines mounted in their entirety with mountings & frames in good condition. A number of tube expander mountings replaced. The latter mounted under steam & their safety valves adjusted to slow steaming.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, B&M.S. 9.11, *L.M.C. 9.11, *CS 9.34, *L.M.C. 140 lb., F.D., &c.)

Globe in my opinion to remain as classed in fresh record of D.S. 1.41.

Survey Fee (per Section 29) £ 8.0.0

Fees applied for 1941

Special Damage or Repair Fee (if any) £ : /

19

Travelling expenses (if chargeable) £ : /

Received by me,

Committee's Minute TUE. 28 JAN 1941

THE 25 FEB 1941

Assigned Deferred

Deferred


(1000 £ 5.40 3d)

B.S. 1.41

19

Warden

S. S. No. 1-40



© 2020
Engineer Surveyor to Lloyd's Register of Shipping.

WII53-0041

Lloyd's Register Foundation

W.D. due 7.40 for

It is submitted that
this vessel is eligible for
THE RECORD. P.D. 1.41.

It is concluded the ice breaking
arrangements are in order ^(Mo. No. 3114)
but the should be confirmed

True
27.1.41

Note. Examination of
sea connections aspect
L.S.