

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office, 20 JUN 1941)

Date of writing Report 2.5.41 When handed in at Local Office 2.5.41 Port of Buenos Aires
 No. in Reg. Book 84668 Survey held at Buenos Aires Date, First Survey 15.4.41 Last Survey 30.4.1941
 on the Machinery of the Wood, Iron or Steel S.S. "TENKESBURY" (No. of Visits 6)
 Tonnage Gross 4601 Vessel built at Stockton By whom Braig, Taylor & Co. Ltd. Year. Month. 1927 11
 Net 2810 Engines made at Stockton By whom Blain & Co. (1926) Ltd. When 1927
 Nominal Horse Power 417 Boilers, when made (Main) 1927 (Donkey) ✓
 No. of Main Boilers 3 Owners Alexander Shipping Co. Ltd. Owners' Address Port London. Voyage United Kingdom
 No. of Donkey Boilers ✓ Managers Capper Alexander & Co. (If not already recorded in Appendix to Register Book.)
 Steam Pressure in Main Boilers 180 lb. # Surveyed Afloat in Dock New Port C 10
 in Donkey Boilers ✓ (State name of Dock.)

Last Report No. PortParticulars of Examination and Repairs (if any) Damage

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined Offered and declined

Was a damage report made by anyone else? If so, by whom? No Underwriters SurveyDid the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

" " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Date latest date of internal examination of each boiler

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Has screw shaft now been drawn and examined? NoIs it fitted with continuous liner? ✓Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓Has shaft now been changed? ✓ If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner? ✓Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? ✓

So, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Is the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Damage stated to have been sustained by enemy action at sea on the 1st March 1941.

Now Done :- HP Main engine lagging covers on cylinder tops crushed renewed
 Weir Feed Heater

Flange on feed pipe adjoining heater crushed, renewed & pipes tested on completion
 Two pressure gauges, cocks & pipes broken renewed

Overflow pipe broken, renewed

Heater opened out examined with mountings & all found in good order.

Handrails, stanchions & grating in way of heater damaged, repaired

General Observations, Opinion, and Recommendation:— The machinery of this vessel, so far as now seen is in a safe working condition, eligible in my opinion to remain as classed, without fresh record of survey.

Survey Fee (per Section 29) £ : : Fees applied for 2.5.41
 Special Damage or Repair Fee (if any) \$53.00
 (per Section 29.)
 Travelling expenses (if chargeable) \$8.00
 Received by me, 19

Committee's Minute

Assigned

FRI. 4 JUL 1941

Deferred

J. A. Orde

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
 Foundation

It is submitted that this vessel WILL BE eligible for the record. — B.S. 241 when cargo values have been adjusted

Damage due to enemy action
H.P. Cylinder lagging & heat
damaged. Now repaired

Yours

1. 7. 41

© 2020

Lloyd's Register
Foundation