

REPORT OF SURVEY FOR REPAIR

Date of writing Report 9-3-42. When handed in at Local Office 19. Port of Beirut

No. in
Reg. Book

Lloyds
+10041

st Survey

SS

When

In Appendix to K

Argo

age

of Classification

as in Register B

ER.
Survey
vey and of
irveys.

71-6.4

0.3-9.33

0.1-39.

rd (if assigned
p and now ve

whom ?

er Items :-

Copper, or Y.M.

(State if on Fe

When fitted, Mor

Boats

Masts, Yards, &c.

Condition, how as

(State if wedges

Equipment letter

Anchors, No. of

Cables (State if now

length

(on bo

Rule length

Chain Locker

Hawsers & Warps

Standing and Runni

ails

in the Register B

main as classed ar

THIS IS TO CERTIFY THAT I, ANDREW PHILIP ROBINSON

Master Mariner of Beirut did today at the request of Messrs.,

J.V. Delbourgo & Son Lloyds Agents of Beirut, go on board the

Greek Steamer "CHRISTOS MARKETOS" of 5209.48 gross tons Gerassimos

Kokolis Master the vessel then lying afloat at the East Quay in

this Port to examine and inspect the damage said to have been

caused by the discharge of her cargo, the same consisting mainly

of full length railway metals and chairs. The following was

ascertained by examination both as to damage and circumstances:

No. 1 Hold.

1 hatch beam cleat on port side slightly bent recently.

5 bilge boards on port side damaged and broken - two recently

1 bilge board on starboard side broken.

1 bilge board on starboard side set down recently.

Many cement plugs on port side at bilges, between frames
broken - 4 recently.

2 cement plugs on port side at bilges, between frames broken
in recently.

17 cement plugs on starboard side at bilges, between frames,
damaged - 4 recently.

30 feet of spar ceiling 6 inches by 2 inches damaged -
apparently recently.

No. 2 Hold.

Tank top in space between 13th and 14th. floors forward
from No. 2 after bulkhead was sharply indented in two places, and
pierced in a third. Several rivets were found to be started,
and the plate surface set down in this area.

The hold ladder was not secured to the lugs on the
tank top, and it was bent and slightly twisted over its whole
length. Only one bolt held its upper end, and this bolt was
very loose, though apparently sound. One or more of the missing
bolts appeared to have been broken recently, though there was



© 2020

Lloyd's Register
Foundation

W1160-0146 1/4

REPORT OF SURVEY FOR REPAIR

Date of writing Report 9-3-1942. When handed in at Local Office 1942.

Port of

No. in
Reg. Book

st Survey

no evidence of recent damage to the ladder itself. The studs holding the ladder lugs on the tank top were found to have been started, though two of these had evidently been sheared off for some long time.

There was no evidence of damage to spar ceiling.

5 beam cleats slightly bent at tween deck coamings.

4 beam cleats out of true on upper coamings, two being fractured. Two of these out of true showed signs of recent blows.

Hatch bearing flange slightly set up in two places recently.

No. 4 Hold.

2 hatch beam cleats slightly out of true.

4 cement plugs at bilges between frames broken in recently.

1 cement plug at bilges between frames, cement broken recently.

26 feet of 6 inches by 2 inches spar ceiling recently broken.

After, fore and aft bulkhead planks broken, possibly recently for a height of about seven feet and for a length of about 6 feet. Timber 3 inches by 9 inches.

No. 5 Hold.

2 hatch beam cleats out of true, one fractured and closed.

Fracture not of recent date.

5 cement plugs at bilges broken in recently.

8 cement plugs at bilges damaged.

1 bilge board fractured. Old fracture.

5 bolts missing from shaft tunnel plating.

The damage detailed was principally normal wear and tear, and except where otherwise stated, does not appear to be of recent origin.

It is recommended that the damage to No. 2 tank top be repaired by welding a small plate over the place pierced, the level made up with cement where the plating is set down, and a doubling plate welded over the area. Also that the hold ladder lugs be

In Appendix

Age

of Classification
as in Register

ER.
Survey.
vey and of
urvey.

71-6

0.3-9.3

0.1-39

rd (if assign
p and now

whom?

er Items:—

Copper, or Y.M.
(State if on
When fitted,

Boats

Masts, Yards,

Condition, how
(State if we

Equipment letter

Anchors, No. of

Cables (State if

length

(on

Rule leng

Chain Locker.

Hawsers & War

standing and Run

Sails.

in the Register
main as classed



© 2020

Lloyd's Register
Foundation

W1160-0146 2/4

Date of writing Report 9-3-1942 When handed in at Local Office 19 Port of Beirut

No. in Reg. Book. Sur

removed, the stud holes welded, and the lugs be refastened by welding, after being faired.

DATED at Beirut this 9th. day of March, 1942.

A. P. Robinson
A. P. ROBINSON.
Master Mariner.
Surveyor to Lloyds Agent.

In Appendix to
Arg

age.

of Classification
as in Register

ER.
Survey.
vey and of
irveys.

71-6.

0.3-9.33

0.1-39.

rd (if assign
p and now

whom?

er Items :-

Copper, or Y.M.
(State if on
When fitted, M

Boats

Masts, Yards, &

Condition, how

(State if wedg

Equipment letter

Anchors, No. of

Cables (State if n

length

(on b

Rule lengt


Chain Locker

Hawsers & Warp

Standing and Run

Sails

in the Register
main as classed



© 2020

Lloyd's Register
Foundation

W1162-0146 3/4

THIS IS TO CERTIFY THAT I, ANDREW PHILIP ROBINSON
Master Mariner of Beirut did today go on board the Greek Steamer
"CHRISTOS MARKETOS" now lying in this Port, and found that the
recommendations made had been soundly and efficiently carried
out.

It is my considered opinion that the vessel is now
in a fit and seaworthy condition to proceed normally on her
voyage until such time as permanent repairs can reasonably
be carried out.

DATED at Beirut this 10th. day of March, 1942.

A. P. Robinson
A.P. Robinson.
Master Mariner.
Surveyor to Lloyds Agent.

orded in Appe
to. A

Voyage...

ars of Clas
ciously as in R

ARACTER.
Special Survey,
st Survey and of
ical Surveys.

AI-

No. 3-9

No. 1-

board (if
Ship and

, by whom

Other Items

Copper, or
(State
When fitt

Boats

Masts, Yan

Condition,
(State i

Equipment

Anchors, N

Cables (Sta

" leng

" Rule

Chain Lock

Hawsers &

Standing an

Sails

essel in the Reg
to remain as cla



© 2020

Lloyd's Register
w 1160-0146 4/4
Foundation