

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 17 JUN 1942)

Date of writing Report 14th May 1942 When handed in at Local Office 16.5.42 Port of Glasgow
 No. in Reg. Book 18947 Survey held at Glasgow Date. First Survey 8.5.42 Last Survey 14.5.42 (No. of Visits 3)
 on the Machinery of the Wood, Iron or Steel "ALDERS DALE"

Tonnage { Gross 8402 Vessel built at Birkenhead By whom Cammell Laird & Co When 1937-9
 Net 5009 Engines made at Sunderland By whom Wm Duffell & Co When 1937
 Nominal Horse Power 687 Boilers, when made (Main) (Donkey) 1937
 No. of Main Boilers 1 Owners The Admiralty Owners' Address (if not already recorded in Appendix to Register Book.)
 No. of Donkey Boilers 2 Managers Port London Voyage -
 Steam Pressure in Main Boilers 150 lbs. If Surveyed Afloat or in Dry Dock held in dry dock (State name of Dock.)

Last Report No. Port
 Particulars of Examination and Repairs (if any) duking, T.S.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom? No.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No.

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time? No.

If this was not done, state for what reasons not done

And what parts of the Boilers could not be thus thoroughly examined? -

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -

State latest date of internal examination of each boiler. - Present condition of funnel(s) -

Did the Surveyor examine the Safety Valves of the Main Boiler? - To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine the Safety Valves of Donkey Boiler? - To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? -, and of the Donkey Boilers? -

Did the Surveyor examine the drain plugs of the Main Boilers? -, and of the Donkey Boilers? -

Did the Surveyor examine all the mountings of the Main Boilers? -, and of the Donkey Boilers? -

Has the screw shaft now been drawn and examined? yes Is it fitted with continuous liner? yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

Has shaft now been changed? no If so, state reasons -

Has the shaft now fitted been previously used? - Has it a continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -

State date of examination of Screw Shaft 14.5.42 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 3/32"

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted -

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? -

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? -

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Vessel placed in dry dock. Propellers, Sea and propeller fastenings examined.

Tail shaft drawn, examined and found in safe working condition.


General Observations, Opinion, and Recommendation:— The machinery, so far as seen, is in safe working condition and eligible in my opinion to remain as classed with full record of Tail Shaft seen (C.L.) 5.42
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, E.&M.S. 9,11, & L.H.C. 9,11, or L.H.C. 140 lb., F.D., &c.)
 US 8,34.

Survey Fee (per Section 29) £ : : Fees applied for 19
 Special Damage or Repair Fee (if any) £ : :
 Travelling expenses (if chargeable) £ : :
 Received by me, B. H. Hasdwell

Committee's Minute GLASGOW 16 JUN 1942
 Assigned As usual
5.42

CHARACTER of Special Survey Date of last Survey and of Periodical Surveys.	Year assigned how long expired.	Machinery and Boiler Surveys (including date of N.D., if any).
+100 A.1		T.L.M.C. 9.37
12.41		D.B.S. 11.41
		T.S. (C.L.) 11.38

Carrying Petroleum in bulk.
OIL ENGINE CONTINUOUS SURVEY



Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to W1165-00152

PS no 1 due 9.4

Notid

4Rw

29.6.42

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the page]



M.V. "ALDERSDALE"

and plate in strake below heated and fused in place, plots riveted & standing caulked.
The riveting and caulking in way of the other indents were examined and overhauled as necessary.

DOCKING.

Vessel placed in dry dock, bottom and rudder cleaned, examined, now satisfactory and recoated.

Decks, casings, hatches, coamings ventilators etc examined and found satisfactory
N.B. Cargo tanks generally examined & found satisfactory.

Freeboard rough checked.

The cables were ranged, anchors & cables examined and now satisfactory.

Chain Locker examined and now satisfactory.

This vessel is not fitted with rod and chain steering gear. Emergency steering gear generally examined and found satisfactory.

REPAIRS. WEAR. AND TEAR.

SHELL. Several rivets in way of aft peak tank (p.r.) set up and electrically welded.

Leakage in way of rudder trunk, made tight by electric welding.

Collar plate in way of port house pipe renewed.

Boat. Deck supports, port side removed, fused and refilled, one angle renewed.

CHAIN LOCKER, PORT SIDE. forward bar of cable fastener removed, fused and refilled. Cable fastener now satisfactory.

Cables. several slack studs tightened up.

S.R.LIST. Shell plates. (P.S.) F.6 (E.W. 12A1) and F.4 and 8. (corrosion) were examined and found efficient. There is no evidence of further corrosion having taken place.

LICENCE. N^o R. 4026. Plans supervised.

W1165 - 0008 2 1/2



© 2020

Lloyd's Register
Foundation