

## REPORT OF SURVEY FOR REPAIRS, &amp;c., OF ENGINES &amp; BOILERS

(Received at London Office)

22 OCT 1942

Date of writing Report August 20<sup>th</sup> 1942 When handed in at Local Office Port of - Balenka.

No. in Survey held at Tw. Sc. M.U. "TASMANIA" Date. First Survey 13.8.42. Last Survey 20.8.42 19 (No. of Visits 2.)

Reg. Book 3337 on the Machinery of the Steel Vessel built at Copenhagen. By whom Ugelsess By whom Det. Sundeboer When 1935. Month 10.

Gross Tonnage 6405. Engines made at Copenhagen. Boilers, when made (Make) Ugelsess Owners' Address Det. Sundeboer (Donkey) 1935.

Nominal Horse Power 6405. Owners T. J. Sundeboer Managers T. J. Sundeboer Surveyed Afloat in Dry Dock (State name of Dock.)

No. of Main Boilers 1 No. of Donkey Boilers 1 Steam Pressure in Main Boilers 100 in Donkey Boilers 100

Last Report No 3083 Port C.T.N.

Particulars of Examination and Repairs (if any) D.S. C.S.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules.) State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey

If this was not done, state for what reasons

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of these parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Has the screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Ins done:- Donkey boiler examined internally externally with mountings found in good condition. Boiler afterwards seen under steam safety valve adjusted. Oil fuel equipment seen under working conditions.

C.S:- The following items have been examined as part C.S. found in good condition:-  
1st Start main engine cylinder, liner, valves, piston rod.  
2nd (Port aft) Auxiliary engine & frame in their entirety.

## General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.&M.S. 9, 11, \*L.M.C. 9, 11, or \*L.M.C. 140 lb., F.D., &c.)

The machinery of this vessel as far as has been seen is in good condition. Slip the in my opinion to remain as classed & to have record D.S. 8.42 C.S. (with date) taken. The survey is complete.

Survey Fee (per Section 29) Rs. 130/- Fees applied for 20.8.1942

Special Damage or Repair Fee (if any) Rs. : Received by me, 19.

Travelling expenses (if chargeable) Rs. :

Committee's Minute Assigned

TUE. 3 NOV 1942

Deferred for mch. repairs

DB 8.42

W1179-0094

Engine Surveyor to Lloyd's Register of Sh

Lloyd's Register Foundation



See also enclosure on  
Cal 114 98.

It is submitted that  
this vessel is eligible for  
THE RECORD.

AMS 642

How

2.11.42



© 2020

Lloyd's Register  
Foundation