

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report

When handed in at Local Office

17 JUN 1940

Port of

HULL

No. in Survey held at

goole

Date, First Survey 27.5.10

Last Survey

11.6.1940

(No. of Visits 5.)

g. Book.

on the

Steel M.V. "ALDERIYQUEEN"

2049

TONNAGE:

GROSS

UNDER D.K.

NET

Built at Leith

By whom Henry Holt, Ltd.

When 1936 - 11

YEAR.

MONTH.

Owners Brit. Channel Stand. Chff. Co., Owners' Address

(if not already recorded in Appendix to Register Book).

Managers

Port belonging to London.

Surveyed in Dry Dock

Name of Dock Goole N°2 D.81. Destined Voyage

Gross D.B. D.Ba

tional capacity

feet; uE&B

feet; f

tons. F.P.T

tons; A.P.T

tons; M.T

feet tons.

only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 98004 Port New

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Survey should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined Offered to Owner

Cpl. not required.

Was a damage report made by anyone else? If so, by whom? Hathaway SurveyorPAIRS, OR EXAMINATION AS PER RULE, FOR Damage + Condition

Damage stated to have been caused by striking submerged rock (Platte Bank) on Sunday 19th May 1940 at 2.20/mu whilst en voyage from London to Guernsey.

Vessel Done:- Vessel placed in dry dock.

Bottom & rudder cleaned & examined, found or placed in good order & afterwards re-coated.

The following damage repairs have now been satisfactorily carried out:-

see continuation sheet.

MARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed	9	3	/	1	/	/	/	see report.
Removed and Fair'd or Repaired	2	33	/	28	/	/	/	
Fair'd or Repaired in place	4	13	/	14	/	/	/	

ENT CONDITION OF THE

	Good		Good		Good		Copper, or Y.M. (State if on Felt.)
Bulkheads		Bulkheads		Engine Room Skylights		-	When fitted, Month Year
Ceiling	"	Ceiling	"	Coal Bunkers, Openings, Covers, &c.		-	
Cement	"	Cement	"	Oil Bunkers		-	
Rudder	"	Rudder	"	Scuppers		"	
Steering gear and its connections	"	Steering gear and its connections	"	Cargo Hatchways		"	
Windlass	not sprung up	Windlass	"	Hatches		"	
Have pumps been examined and found efficient?		Have pumps been examined and found efficient?		Planking			
Have Sluice Valves been examined and found efficient?		Have Sluice Valves been examined and found efficient?		Gauking			
Have Watertight Doors been examined and found efficient?		Have Watertight Doors been examined and found efficient?		Treenails			
Have Ventilators and their Coamings been examined and found efficient?		Have Ventilators and their Coamings been examined and found efficient?		Breasthooks & Stemson			
Air and Sounding Pipes		Air and Sounding Pipes		Transoms, Pointers & Crutches			
Doubling Plates under Sounding Pipes		Doubling Plates under Sounding Pipes		Timbers of Frame at openings			
				" at other places			
				Stringers, Clamps & Shelves			
				Sailing			
				(State if examined.)			

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1-38," or "to remain as classed and to have record of survey, 1-38, and the notations of No. 1-38."

is vessel, so far as now seen, is in an efficient condition, and eligible, in my opinion, to remain as classed, with fresh record of 1-40, subject to bottom of vessel in motor space being specially examined internally when in dry dock (cement omitted) as previously recommended.

Survey Fee (per Section 28) Damage £ 16 : 16 : 0 Fees applied for,

Special Damage or Repair Fee (if any) £ per Sec. 28

Travelling Expenses (if chargeable) £ 1 : 19 : 4 Received by me,

Second Surveyor's Fee (if any) £ : :

17 JUN 1940

19

Committee's Minutes

Character Assigned

Wickesby Hm

FRI. 28 JUN 1940

100A1
Cargo bats. not fitted

R. Hollard, Surveyor to Lloyd's Register of Shipping 2020

Lloyd's Register Foundation

M.V. "ALDERNEY QUEEN"

KEEL: - Nos 1, 2, & 3 plates removed.

SHELL: - PORT SIDE:-

A STRAKE, Nos 2 & 3 plates removed. No 4 plate fairied in place.

B STRAKE, No 2 plate fairied in place.

STARBOARD SIDE:-

A STRAKE, No 3 plate fairied in place.

Nos 4, 5, & 6 plates removed.

B STRAKE, Nos 4 & 5 off, fairied & refitted.

No 6 plate removed.

C STRAKE, No 7 plate fairied in place.

FOREPEAK:-

3 floors O.F.R.

3 main frames cropped & part removed.

3 doublung frames O.F.R.

2 intercostals with floor and shell lugs removed.

1 intercostal fairied in place.

2 intercostal shell lugs fairied in place.

N°1 TANK, PORT SIDE

Forward end plate cropped & part removed.

1 floor O.F.R.

6 frames O.F.R.

1 intercostal plate O.F.R.

1 intercostal floor angle O.F.R.

1 intercostal shell angle O.F.R.

5 floors and frames F.I.P.

1 floor removed.

2 intercostal plate & lugs O.F.R.

1 floor crop & part removed.

1 floor fairied in place.

Centre keelson bottom angles cropped & part removed.

1 centre keelson plate F.I.P.

3 centre keelson floor lugs O.F.R.

STARBOARD SIDE

13 floors O.F.R.

13 frames O.F.R.

13 centre keelson lugs O.F.R.

13 intercostals and lugs O.F.R.

1 tank end floor O.F.R.

1 tank end frame O.F.R.

N°2 TANK, STARBOARD SIDE

10 floors O.F.R.

10 frames O.F.R.

4 centre keelson lugs off fair & refit.

Rpt. 9a.

Port of

HULL

Continuation of Report No. 50732 dated

11.6.40.

on the

M.V. "ALDERNEY QUEEN"

10 intercostals and legs OFR.

8 frames & floors FIP

6 centre bulkhead lugs OFR

A number of defective shell rivets removed.

Ceiling lifted as necessary for access to repairs & replaced.

Tone peak & double bottom tanks tested on completion.

Steering gear chains annealed & tested.

Condition: Decks, casings, coamings, holds, hatches, vents, generally examined & found satisfactory.

Rudder lifted & 2 bushes renewed.

Minor repairs effected.

J.M. Stonehouse