

REPORT OF SURVEY OR REPAIRS, WRECK

Date of writing Report 19... When handed in at Local Office 28 MAR 1940 Port of FULL No. 391

No. in Reg. Book 29657 Survey held at Hull Date, First Survey and Last Survey 11. 3. 1940

Tonnage:— Built at Newcastle By whom Northumbrian S.B. Co. Ltd. When 1920 - 10

GROSS 5141 Owners Bout Line Ltd. Owners' Address (if not already recorded in Appendix to Register Book).

UNDER DE. 4900 Managers Haldin & Philpotts Ltd. Port belonging to London.

NET 3217

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Alexandra Destined Voyage

Cell DBor DBa feet; uE&B feet; f feet

total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 7378 Port Mel

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR SR List. See Sydney Rpt. no 17369 & Melbourne Rpt. no. 7378.

Examine shell deck plate (port side amidship) abreast machinery casing (EW 12.39) & extend electric welding full breadth of plate (as showing grooving) as a temporary repair. In turn deck, port side, bunker deck plate found holes locally: an efficient doubling plate electric welded as a temporary repair. The deck fittings indicated in Sydney Rpt. no. 17369 have now been dealt with except those items already done at Melbourne.

The other items of SR List have not been dealt with here. Owners' representative stated the vessel was urgently required for Government service for a short voyage to Norway & back to U.K. and that because of this the S.S. 2nd No 1 could not be done now but that the special survey would be done on vessel's return to this country within one month's time.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								
PRESENT CONDITION OF THE								
Decks	Surf. - efficient	Bulkheads	✓	Engine Room Skylights	Efficient	Copper, or Y.M.	✓	(State if on Felt.)
Caulking of Decks	✓	Ceiling	✓	Coal Bunkers, Openings, Covers, &c.	Surf. - efficient	When fitted, Month	Year	
Coamings	Efficient	Cement or Asphalt	✓	Oil Bunkers	✓	Boats	Part th' - good	
Seams & Fastenings	Part th' - efficient	Rudder	✓	Scuppers	✓	Masts, Yards, &c.	Efficient	
Outside Plating	✓	Steering gear and its connections	Gen. efficient	Cargo Hatchways	Part th' - efficient	Condition, how ascertained	From deck	
" " in way of sidelights	✓	Windlass	✓	Hatches	✓	(State if wedges removed)		
Frames	Part th' - efficient	Have pumps been examined and found efficient?	✓	Planking	✓	Equipment letter	✓	
Reverse Frames	✓	Have Sluice Valves been examined and found efficient?	✓	Caulking	✓	Anchors, No. of	✓	
Longitudinals	✓	Have Watertight Doors been examined and found efficient?	✓	Treenails	✓	Cables (State if now ranged)	✓	
Transverses	✓	Have Ventilators and their Coamings been examined and found efficient?	✓	Breasthooks & Stemson	✓	" length	mean diam.	✓
Floors	✓	Air and Sounding Pipes	Part th' - efficient	Transoms, Pointers & Crutches	✓	" (on board)	size	✓
Keelsons	✓	Doubling Plates under Sounding Pipes	✓	Timbers of Frame at openings	✓	" Rule length	size	✓
Stringers	✓			" " at other places	✓	Chain Locker	✓	
Inner Bottom Plating	✓			Stringers, Clamps & Shelves	✓	Hawsers & Warps	✓	
Have the Tanks been examined internally?	✓			Salting	(State if examined.)	Standing and Running Rigging	✓	
Have the Tanks been tested?	✓					Sails	✓	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

Eligible to remain as classed without fresh record of survey subject to indented bottom plating (S.S. 2) and indented side plating (p.s. amidship & forward) being dealt with & riveting of one intercostal shell angle bar in no. 10.B. tank (S.S.) being repaired at Owners' convenience and to shell deck plate (p.s. amidship) abreast machinery casing (EW 12.39 & 3.40.) and port turn deck plate being permanently dealt with at S.S. without other condition.

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	2	2	28 MAR 1940
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute
Character Assigned

FRI 12 APR 1940

Deferred for 2d. No. 1 Rpt. 8.39

W.S. Shields
Surveyor to Lloyd's Register of Shipping.



© 2021

Lloyd's Register Foundation

W182-0090