

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

MAR 14 1941

Date of writing Report 7.3.41 When handed in at Local Office 11.3.41 Port of BRISTOL

No. in Reg. Book 76406 Survey held at AVONMOUTH Date, First Survey 10.2.41 Last Survey 5.3.1941
 on the Machinery of the Wood, Iron or Steel "INVERSUIR" (No. of Visits 4)

Tonnage Gross 9456 Vessel built at HAMBURG By whom DEUTSCHE WERFT. A.G. BET. FINKENWÄDER When 1938 Month 11
 Net 5561 Engines made at AUGSBURG By whom MASCHINENFAB. AUGSBURG-NÜRNBERG 1938

Nominal Horse Power 997 Boilers, when made (Main) (Donkey) 1938

No. of Main Boilers 2 Owners INVER TANKERS, Ld. Owners' Address (if not already recorded in Appendix to Register Book.)
 No. of Donkey Boilers 108 Managers A. WEIR & Co., Port GLASGOW Voyage
 Steam Pressure in Main Boilers 5 Surveyed Afloat 5 in Dry Dock Royal Edward D. Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boilers 180 lbs.

Last Report No. Port Particulars of Examination and Repairs (if any) Comp. of LMC(M) Docking.

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

" " Donkey " " " " ✓
 If this was not done, state for what reasons? DBS. not done

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler ✓

Present condition of funnel(s) ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓

To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓

To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓

, and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons ✓

Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft ✓ State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 1/16"

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? ✓

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

For commencement of the LMC(M) survey see Bristol Rpt. No. 14616.

Now Done for Completion of LMC(M): The following machinery parts opened up & examined -

Main Engine - Nos 4 & 8 crank pins & bottom end bearings. Nos 4, 5, 8 & 9 crank journals & main bearings. No 2 intermediate shaft journal. Starting air receivers (2) internally.

Examined so far as practicable, aux. air compressors (2). Circulating pumps & lubricating oil pumps and these were subsequently examined under working conditions.

Docking: Vessel placed in dry dock. Examined propeller, aft. end of stern bush and fastenings of all underwater connections. All found & placed in good condition.

General Observations, Opinion, and Recommendation: The machinery of this vessel is in

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0, 11, D.M.S. 0, 11, & L.M.C. 0, 11, or L.M.C. 140 lb., F.D., &c.)

good condition so far as now seen and eligible in my opinion to remain so classed with fresh record of LMC(M) 3-41.

Survey Fee (per Section 20) Comp. LMC(M) £ 7 : 0 : 0 Fees applied for 19

Special Damage or Repair Fee (if any) (per Section 20.) £ Received by me, 19

Travelling expenses (if chargeable) £ 4 : 0 :

Committee's Minute FRI. 28 MAR 1941

Assigned Adm. b. (M) 12.40

© 2020
 Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
 Foundation

W1196-0026

Not Survey
Completed.

Value (W) 12.40.

9. Fees.
Three fees is £7.
27 charged now 26/9/41.
£23 in 12.40

25/9



© 2020

Lloyd's Register
Foundation