

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

DEC 27 1939

Date of writing Report 22nd Dec. 1939

When handed in at Local Office

22 DEC 1939

Port of

NEWPORT, MON.

No. in
Reg. Book.

Survey held at

NEWPORT, MON.

Date, First Survey

14th Dec.

Last Survey

22nd Dec. 1939

(No. of Visits 5)

30479 on the Machinery of the Wood, Iron or Steel

S.S. "NIOBE"

Tonnage

Gross 1684
Net 884

Vessel built at

Beyth

By whom

Beyth S.B. & Co. Ltd.

When

1920-8

Nominal
Horse Power

244

Engines made at

Sunderland

By whom

N.E. Marine Eng. Co.

When

"

No. of Main Boilers

2

Boilers, when made (Main)

1920

(Donkey)

No. of Donkey Boilers

1

Owners Societe Havale Baennais

Owners' Address

(if not already recorded in Appendix to Register Book.)

Managers G. Lamy & Co

Port

Baen

Voyage

Steam Pressure

190

If Surveyed Afloat or in Dry Dock

Baen 0.04. 1939

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No.

Port

B.S.

Particulars of Examination and Repairs (if any). Prop. 1. 1939

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

R.B.R. 14/12/39

S.B. 19/12/39

Present condition of funnel(s)

efficient

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

190 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boiler?

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

3/16

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Vessel in dry dock. Propeller, all outside fastenings examined and found in order.

Main Boiler opened out, examined together with their safety valves, other mountings, found in good order. Repair, P. Boiler - 2. Screw shaft renewed, 7 stay bolts renewed, a number of tubes in Port, Star. Boiler expanded. All safety valves adjusted under steam and found satisfactory.

General Observations, Opinion, and Recommendation:—The Machinery of this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, E.&M.S. 9, 11, & L.M.C. 9, 11, or

*L.M.C. 140 lb., E.D., &c.)

so far as now seen is eligible to remain as classified with Record of B.S. 12. 39.

Survey Fee (per Section 29)

B.S.

£ 3.0.0

Fees applied for

22 Dec 1939

Special Damage or Repair Fee (if any) (per Section 29)

£

Received by me,

Travelling expenses (if chargeable)

£

19

Committee's Minute

Assigned

FRI 19 JAN 1940

B.S. 12. 39

CERTIFICATE WRITTEN

D.W. Carpenter

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W1200-0025