

No. 0399⁶

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

WED. 8 JUN. 1921

Report made at Amsterdam on the 3rd Jun. 1921. When handed in at Local Office in Port of Amsterdam Date, First Survey April 5. Last Survey Jun. 2 1921

on the Machinery of the Wood, Iron or Steel Twin Screw Steam Driven Master (Capt. Kappelin) No. of Visits 4 YEAR MONTH

Vessel built at B. Tegesack By whom Bremse (Capt. Kappelin) When 1914

Engines made at Negerack By whom Bremse (Donkey) When 1914

Boilers, when made Main Owners Orient Steam Navigation Co. Ltd. Port London Voyage London

If Surveyed Afloat or in Dry Dock (State name of Dock)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Port No. 14147 Port Amsterdam

Particulars of Examination and Repairs (if any) Contemplated

When held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were not accepted.

Was a damage report made by anyone else? If so, by whom?

Did you personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Did you personally go inside each Donkey Boiler separately and make a thorough examination at this time? Yes

Were the Main Boilers examined, state for what reasons? Yes

Were the Donkey Boilers examined, state for what reasons? Yes

Were the Safety Valves of the Main Boilers examined? Yes

To what pressure were they afterwards adjusted under steam? 100 A. Contemplated

Were the Safety Valves of Donkey Boilers examined? Yes

To what pressure were they afterwards adjusted under steam? Shocks etc.

Were all the manholes, doors and their fastenings of the Main Boilers examined? Yes

Were the manholes, doors and their fastenings of the Donkey Boilers examined? Yes

Were the drain plugs of the Main Boilers examined? Yes

Were the drain plugs of the Donkey Boilers examined? Yes

Were all the mountings of the Main Boilers examined? Yes

Were the mountings of the Donkey Boilers examined? Yes

Has the Main Boiler been drawn and examined? Yes

Is it fitted with continuous liner? Yes or two liners? Yes or is it without liners? Yes

Has the Donkey Boiler been drawn and examined? Yes

Is it fitted with continuous liner? Yes or two liners? Yes or is it without liners? Yes

Has the space between the lignum vitae of stern bush and top of after bearing of screw shaft been examined? Yes

Is the examination complete? Yes state what arrangements have been made for its completion and what remains to be done? Refer Afloat.

Were the Piston Rods, Piston Rings, Piston Skirts, Thrust and Tunnel Shafts examined? Yes

Were the Crank Pins, Crank Shafts, and Crank Webs examined? Yes

Were the Main Bearings examined? Yes

Were the Donkey Bearings examined? Yes

Were the Piston Rods and Springs examined? Yes

Were the Piston Rings examined? Yes

Were the Piston Skirts examined? Yes

Were the Thrust and Tunnel Shafts examined? Yes

Were the Crank Pins, Crank Shafts, and Crank Webs examined? Yes

Were the Main Bearings examined? Yes

Were the Donkey Bearings examined? Yes

Were the Piston Rods and Springs examined? Yes

Were the Piston Rings examined? Yes

Were the Piston Skirts examined? Yes

Were the Thrust and Tunnel Shafts examined? Yes

Were the Crank Pins, Crank Shafts, and Crank Webs examined? Yes

Were the Main Bearings examined? Yes

Were the Donkey Bearings examined? Yes

Were the Piston Rods and Springs examined? Yes

Were the Piston Rings examined? Yes

Were the Piston Skirts examined? Yes

Were the Thrust and Tunnel Shafts examined? Yes

Were the Crank Pins, Crank Shafts, and Crank Webs examined? Yes

Were the Main Bearings examined? Yes

Were the Donkey Bearings examined? Yes


Fee charged for 1st entry 21.50
for 2nd entry 21.50
for 3rd entry 21.50

Sees applied for 19
Received by me 19

See's Minute
no action

TUE. 13 DEC. 1921
TUE. 22 AUG. 1922
FRI. 13 APR. 1923

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W1218-0172

Insert Character of Ship and Machinery precisely as in the Register Book.

This is a certificate required by Lloyd's Register of Shipping.

in after lower and Standard. in. furnace.

Port forward boiler, two saddle welded in after lower furnace as Port wing. Various leaky seams made tight.

All mounting and fitting thoroughly overhauled and examined. Remains to be done for completion of L. M. C.

Examination of Port. L. P. valve and chest.

Port. 2nd. M. P. slide valves.

Both the main condensers to be examined and tested.

Both centrifugal pumps.

Evaporator and distiller to be tested.

All safety valves to be adjusted under steam.

The vessel is now in her way to London at which Port the fitting will be complete.

Proposed fee. /150. As per Secretary. 11th 31-5-21.

In the information of the Committee. F. V. Berridge

Attend to the request of various Representatives to examine and report the fitting of insulation in No. 1, 2 and 3 holds and lower tween deck for the carrying of frozen meat. The refrigerating machinery will be on the CO₂ system and will be fitted at London for which Port the vessel is now due. All air trunks have been supplied and fitted and means provided for all necessary bolts, holes and brackets for the attachment of machinery. Deck top plating insulated with Charcoal 3" thick and covered with two thicknesses white pine secured to white pine grounds 2 1/2" properly spaced and secured. Lower thickness of wood 1 1/2" and upper 1" with two ply insulating paper between. The insulation finished off at the deck side brackets with strong fitted pine boundary plank, top side to take portable limber hatches.

Portable hatches arranged at intervals for examination of margin fittings. Bulkheads insulated 10 1/2" thick, grounds white pine; 2 1/2" thick and full depth of space; lining two thicknesses with pine 1" and 1 1/2" respectively, with two ply of insulating paper and charcoal between. Means adopted for draining holds into bilges. Space for charcoal at ship side 10" space made watertight and air tight. The inner skin two thicknesses with pine 1" and 1 1/2" respectively with two ply insulating paper and charcoal between and nailed to the grounds, secured fitted to frames.

The top of inner skin made portable for running charcoal both on ship side and bulkheads. Tween deck insulated underneath.

Air trunks from air cooler fitted along port and starboard sides with charcoal valves to direct the air supply, hinged to fold up to deck. Insulated removable portions for access to high suction, roses, etc. Thermometer tubes fitted on gun rule, Cayol bottom fittings, Hatchways properly insulated.

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

© 2019 Lloyd's Register Foundation