

DISCLOSED
EX 12-90
Rpt. 9

DISCLOSED
BOX 10

89 Bottom

No. 11086

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

8 MAY 1930

Date of writing Report 5 May 1930 When handed in at Local Office 19 Port of AMSTERDAM
No. in Reg. Book 06778 Survey held at YMUIDEN Date, First Survey 21 March Last Survey 21 April 1930
(No. of Visits 2)
on the Machinery of the WOODEN STEEL Sc.K. "BALDER"
Tonnage { Gross 247 Vessel built at Rotterdam By whom Wilton's E. & Slpwy Co. When 1906-9
Net 87 Engines made at " By whom Wilton's E & Slpwy Co. When 1906
Nominal Horse Power 71 Boilers, when made (Main) 1906 (Donkey) -
No. of Main Boilers 1 SB Owners N.V. Exploitatie en Administratie My. "Shamrock I"
No. of Donkey Boilers - Managers S. Koster (if not already recorded in Appendix to Register Book.)
Steam Pressure in Main Boilers 180 Lb Port Ymuiden Voyage -
in Donkey Boilers - If Surveyed Afloat or in Dry Dock Afloat
(State name of Dock.)

Last Report No. 11780 Port Amst.
Particulars of Examination and Repairs (if any) Compl IMC

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " " " " " " "

If this was not done, state for what reasons? all parts accessible

And what parts of the Boilers could not be thus thoroughly examined? all parts accessible

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Yes

Did the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? 180 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes To what pressure were they afterwards adjusted under steam? -

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes , and of the Donkey Boilers? Yes

Did the Surveyor examine the drain plugs of the Main Boilers? Yes , and of the Donkey Boiler? Yes

Did the Surveyor examine all the mountings of the Main Boilers? Yes , and of the Donkey Boiler? Yes

Has screw shaft now been drawn and examined? no Is it fitted with continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Yes

Has shaft now been changed? Yes If so, state reasons - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Yes

Has the shaft now fitted been previously used? Yes Has it a continuous liner? Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? Yes

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft not seen

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Compl kindly see hrs up 11/3006.

Ex & cylinders, pistons, slide valves, steam chests, crank & thrust shaft including bearings & shoes, etc., circulating feed & bilge pumps including seats & valves found & made good
Condenser opened out & tested as per rules found sound & tight
Auxiliary engines, bilge pump arrangements & valves overhauled & made good.
Ex & Boiler in its entirety same almost as previous & in good working order. Safety valves, mountings & fastenings, manholes & doors good
Nothing has been done to Compl the SH-3 on Hull as per hrs up 11/3006
but it was noted same will be done next month.

General Observations, Opinion, and Recommendation: This vessel's Machinery

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9.11, R.&M.S. 9.11, or L.M.C. 9.11, 140 lb., F.D., &c.)

is in a good & efficient condition & she is eligible in my opinion to remain as classified with notation of IMC 4-30 in the Lloyds' Register Book

Survey Fee (per Section 28) £60.- Fees applied for 19
Special Damage or Repair Fee (if any) £ Received by me, 19
Travelling expenses (if chargeable) £3.00
Committee's Minute FRI 16 MAY 1930
Assigned + Lmb 4.30
Certificate Written BB
Deferred for Comp. 20.10.30
Write for 3 mo

Insert Character of Ship and Machinery precisely as in the Register Book.

Surveyor's Signature

M1226-0014

L. 1803 due 12. 28. Held.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD. + L.M.C. 4.30.

14/5/30

TUE 30 SEP 1930
Grange Affairs
with Red Line

4/10/30

General Committee
Thursday, 2nd October, 1930.

Classing Committee's
decision confirmed

AS
Z
Posted
10/10/30

of St. L. of Wales
30-10-1930

30/10/30
"I am sorry to hear of the death of the late Mr. J. H. Jones, who was a member of the Committee for many years."

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.