

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report April 7th 1933 When handed in at Local Office 7th ap. 1933 Port of Cadix

No. in Survey held at Malagorda Date, First Survey March 23 Last Survey March 23 1933 (No. of Visits one)

1923 on the Machinery of the ~~Wood, Iron or Steel~~ S Trawler "Canosa" ex "Angac"

Name { Gross 316 Net 148 Vessel built at Selby By whom Cochrane & Sons Ltd When 1916

Engines made at Hull By whom C.D. Holmes & Co When 1916

Boilers, when made (Main) 1916 (Donkey)

Owners Vuida de Canosa-Cierlo Owners' Address Port Barcelona Voyage

Managers If Surveyed Afloat or in Dry Dock Dry Dock Malagorda (State name of Dock.)

Last Report No. _____ Port _____

Particulars of Examination and Repairs (if any) 2nd n^o 1. S.S.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services or this purpose, and why they were declined

as a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " "

if this was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

So what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boiler?

Has screw shaft now been drawn and examined? yes Is it fitted with continuous liner? yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? no

Has shaft now been changed? no If so, state reasons _____

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 1 7/8

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete

Now done:- Vessel placed in dry dock, Examination made of Propeller, Stern tube stuffing box, Sea connections and underwater fastenings, Tail end shaft drawn in and bush rewooded, all now in good condition.

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, E.S. 9,11, B.&M.S. 9,11, or L.M.C. 9,11, 140 lb., E.P., &c.)

The tail end shaft and stern bush of this vessel is now in good condition and eligible in my opinion to remain as classed with fresh record of Tail end shaft 3-33. The note in Limitation List may now be deleted.

Survey Fee (per Section 29) Rs 45-00 Fees applied for 1. ap. 1933
Special Damage or Repair Fee (if any) £ : : Received by me, 1933
Travelling expenses (if chargeable) £ : :

Committee's Minute PHI 28 APR 1933 Assigned As now Without spl. Cond.
TUE. 20 JUN 1933
FRI. 11 AUG 1933
FRI. 20 OCT 1933
Engineer Surveyor to Lloyd's Register of Shipping.



Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to _____

Scen shaft examined &
stem by wooded.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD. 13-33

without special
condition.

27/4/33

[Faint, mostly illegible handwritten notes in blue ink, possibly bleed-through from the reverse side of the page.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation