

-9 OCT 13 46

(Received at London Office

Tonnage { Gross	Vessel built at <u>Dublin</u>	By whom <u>✓</u>	When
Net	Engines made at <u> Ipswich</u>	By whom <u>Vickers-Peters Ltd</u>	When
Nominal { Horse Power }	Boilers, when made (Main)	<u>✓</u>	(Donkey) <u>✓</u>
No. of Main Boilers	Owners <u>✓</u>	Owners' Address <u>✓</u>	
No. of Donkey Boilers	Managers <u>✓</u>	(if not already recorded in Appendix to Register Book).	
Steam Pressure— in Main Boilers		Port	Voyage
in Donkey Boilers	If Surveyed Afloat or in Dry Dock <u> Messrs Amos & Smith Ltd - Liverpool</u>	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
	(State name of Dock.)		

Particulars of Examination and Repairs (if any) New Year

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do.	"	Donkey	"	"
-----	---	--------	---	---

his was not done, state for what reasons?

1 what parts of the Boilers could not be thus thoroughly examined?

to what special means, in the absence of internal examination, were adopted by the }
surveyor to assure himself of the thorough efficiency of those parts of each Boiler ? }

the Surveyor examine the Safety Valves of the Main Boiler P

1 the Surveyor examine the Safety Valves of Donkey Boiler?

1 the Surveyor examine all the manholes, doors and their fastenings of the Main Bollers?

1. Did the Surveyor examine the drain plugs of the Main Boilers?

1 the Surveyor examine all the mountings of the Main Boilers?

Has a screw shaft now been drawn and examined? Is it fitted with continuous liner?

Has shaft now been changed? ✓ If so, state reasons

the shaft now fitted new? ☒ Has it a continuous liner?

to the distance between lignum vite or bearing metal of stern bush and top of after bearing of screw shaft?

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Messrs. Vickers-Petters Ltd.

Engines 1058. 1059.

The propellers, propeller shafts, intermediate shafts, stern tubes bushes & bearings made by Amos & Smith Ltd for the above engines now satisfactorily completed.

The approved plans & 'forging' reports sent here with

It should be noted for the first entry report, that the annular space between the ^{tail} shaft & the lines, between bearings, has not been filled with plastic material.

It is stated that the above materials have been sent direct to Dublin for installing as bogrod.

General Observations, Opinion, and Recommendation:—The above report is sent for (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,11, B.&M.S. 9,11, or L.M.C. 9,11, 140 lb., F.P., &c.) the information of the Committee, and for guidance in writing the first entry report.

Copy Fee (per Section 28)	£	1	1	Fees applied for
				19
Initial Damage or Repair Fee (if any)	£	1	1	
(per Section 28.)				
Travel Expenses (if chargeable)	£	1	1	Received by me,
				19

Committee's Minute

WED. 8 JUN 1927

signed

See Dub. Isl. rpt. No 4559

Shadrach
Engineer Surveyor to Lloyd's

Engineer Surveyor to Lloyd's Register of Shipping.

© 2021
Lloyd's Regi
Foundation
w1319-0311

This report should be forwarded
to the London (Ld) Surveyor for
his information & guidance

11/10/26.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

© 2021

Lloyd's Register
Foundation

apt. 4b