

Chief Surveyors

Received from Chief Surveyors

S NAME Steel S.S. "SAPINERO". Report Phl. No. 8134

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

f Survey

When due

The chain cables have been tested by the Surveyors to the American Bureau.

100 A.L. (Steel).

2 Dks. (Steel). *Webframes*

Cell DB 270' 1380t. MT 24' 748t. FPT 144t. APT 100t.

EK. 8 BH. Cem. A.P. P39', B122', F43'.

*M*  
5. 4. 19.

It is concluded the frames in peak are 5 X  $3\frac{1}{2}$  X  $\frac{3}{8}$  but the Surveyor should state if this is so.



© 2019

Lloyd's Register  
Foundation

W132-0241