

*Chief Surveyors*

Received from Chief Surveyors

2'S NAME Steel S.S. "WESTPOOL".

## Report

Sea.

No. 747

For the **CHIEF SHIP SURVEYOR** and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/5/52.)

of Survey

When due

The kedge anchor has been dispensed with as a War Emergency Measure.

100 Al. (Steel)

2 Dks. (Steel) & Web frames. Longitudinal framing.

Cell DB. 353', 1174t. DT a 37', 952t. FPT 140t. APT 155t.

FK 7BH. Cem. A & C.P. P41'. B121'. F43'.

8. 1. 19

The Surveyors should state the number of the boats fitted and also whether a Downton or hand-pumps have been supplied, as this information has been omitted from the report.

They should also be informed, it is concluded the deep tank bulkheads on transverses 17 & 18 $\frac{1}{2}$  are .42 of an inch in thickness, but they should state if this is so.

2/11/9

Lloyd's Register 5x5x

W136-0035

<b>BEAMS, Bridge Deck, Angle, Bulb Angle, Plate, )</b>	
Tee Bulb, or Channel.....)	
„    Angles on upper edge .....	
„    Spacing .....	

Forecast for Deck Surface of a 1000 sq. ft. Deck

12	Angle on ditto.. <i>7/16</i> .....	
11	<del>Tie Plates</del> .....	
10	Deck. Material and thickness .....	